

Induction Motors

1 W (1/750 HP), 3 W (1/250 HP)

Frame Size: □42 mm (□1.65 in.)



(Gearhead sold separately)

Specifications – Continuous Rating (RoHS)



Model Lead Wire Type		Output Power W HP	Voltage VAC	Frequency Hz	Current A	Starting Torque mN·m oz-in	Rated Torque mN·m oz-in	Rated Speed r/min	Capacitor μF
Pinion Shaft Type	Round Shaft Type								
Ⓟ OIK1GN-AW3U	OIK1A-AW3U	1 1/750	Single-Phase 110	60	0.074	8	8	1200	1.0
			Single-Phase 115		0.078	1.13	1.13		
Ⓟ OIK3GN-BW3U	OIK3A-BW3U	3 1/250	Single-Phase 110	60	0.115	6	10	3000	1.5
			Single-Phase 115		0.118	0.85	1.42		

- The **U** at the end of the model name indicates that the unit includes a capacitor. This letter is not listed on the motor nameplate. When the motor is approved under various safety standards, the model name on the nameplate is the approved model name. → Page G-11
- Details of safety standards → Page G-2
- Details of RoHS Directive → Page G-38
- Ⓟ: Impedance protected

Product Line

● Motor (RoHS)

Type	Model	
	Pinion Shaft Type	Round Shaft Type
Lead Wire	OIK1GN-AW3U	OIK1A-AW3U
	OIK3GN-BW3U	OIK3A-BW3U

The following items are included in each product.
Motor, Capacitor, Capacitor Cap, Operating Manual

● Parallel Shaft Gearhead (Sold separately) (RoHS)

Gearhead Type		Gearhead Model	Gear Ratio
Parallel Shaft	GN-K Gearhead	OGN□KA	3, 3.6, 5, 6, 7.5, 9, 12.5, 15, 18, 25, 30, 36, 50, 60, 75, 90, 100, 120, 150, 180

- Enter the gear ratio in the box (□) within the model name.

The following items are included in each product.
Gearhead, Mounting Screws, Operating Manual

1 W, 3 W
(1/750 HP,
1/250 HP)6 W
(1/125 HP)15 W
(1/150 HP)25 W
(1/150 HP)40 W
(1/179 HP)50 W
(1/112 HP)90 W
(1/18 HP)200 W
(1/14 HP)2-Pole
40-150 W
(1/19-1/5 HP)

Gearmotor – Torque Table

- Gearheads are sold separately. Decimal gearheads are not available.
- Enter the gear ratio in the box (□) within the gearhead model name.
- A colored background (□) indicates gear shaft rotation in the same direction as the motor shaft, while the others rotate in the opposite direction.
- The speed is calculated by dividing the motor's synchronous speed (4-pole type; 60 Hz: 1800 r/min, 2-pole type; 60 Hz: 3600 r/min) by the gear ratio. The actual speed is 2~33% less than the displayed value, depending on the load.

◇ 60 Hz

Unit = Upper values: N-m/Lower values: lb-in

Model	Speed r/min	600	500	360	300	240	200	144	120	100	72	60	50	36	30	24	20	18	15	12	10
		Gear Ratio																			
OIK1GN-AW3U	OGN□KA	0.019	0.023	0.032	0.039	0.049	0.058	0.073	0.088	0.11	0.13	0.16	0.19	0.26	0.32	0.35	0.42	0.47	0.57	0.71	0.85
		0.168	0.20	0.28	0.34	0.43	0.51	0.64	0.77	0.97	1.15	1.41	1.68	2.3	2.8	3.0	3.7	4.1	5.0	6.2	7.5

Unit = Upper values: N-m/Lower values: lb-in

Model	Speed r/min	1200	1000	720	600	480	400	288	240	200	144	120	100	72	60	48	40	36	30	24	20
		Gear Ratio																			
OIK3GN-BW3U	OGN□KA	0.024	0.029	0.041	0.049	0.061	0.073	0.091	0.11	0.13	0.17	0.20	0.24	0.33	0.40	0.44	0.53	0.59	0.71	0.89	1
		0.21	0.25	0.36	0.43	0.53	0.64	0.80	0.97	1.15	1.50	1.77	2.1	2.9	3.5	3.8	4.6	5.2	6.2	7.8	8.8

Permissible Overhung Load and Permissible Thrust Load

Motor (Round shaft type) → Page A-16

Gearhead → Page A-16

Permissible Load Inertia J of Gearhead

→ Page A-17


Dimensions Unit = mm (in.)

- Mounting screws are included with gearheads. Dimensions for mounting screws → Page A-310

◇ Lead Wire Type

Motor Model	Gearhead Model	DXF
OIK1GN-AW3U OIK3GN-BW3U	OGN□KA	A441U

Mass: Motor 0.3 kg (0.66 lb.)
Gearhead 0.2 kg (0.44 lb.)




Detail Drawing of Protective Earth Terminal

◇ Shaft Section of Round Shaft Type


The motor's dimensions (excluding the shaft section) are the same as those of the pinion shaft types.

Motor Model	Mass	DXF
OIK1A-AW3U OIK3A-BW3U	0.3 kg (0.66 lb.)	A442




- Enter the gear ratio in the box (□) within the model name.

◇ Capacitor (Included)




◇ Capacitor Dimensions Unit = mm (in.)

Model		Capacitor Model	A	B	C	Mass g (oz.)	Capacitor Cap
Pinion Shaft Type	Round Shaft Type						
OIK1GN-AW3U	OIK1A-AW3U	CH10FAUL	31 (1.22)	14.5 (0.57)	23.5 (0.93)	18 (0.64)	Included
OIK3GN-BW3U	OIK3A-BW3U	CH15FAUL	31 (1.22)	14.5 (0.57)	23.5 (0.93)	18 (0.64)	



■ Connection Diagrams

- The direction of motor rotation is as viewed from the shaft end of the motor. CW represents the clockwise direction, while CCW represents the counterclockwise direction.
- Connection diagrams are also valid for the equivalent round shaft type.



PE: Protective Earth

Note:

- Change the direction of single-phase motor rotation only after bringing the motor to a stop. If an attempt is made to change the direction of rotation while the motor is rotating, motor may ignore reversing command or change its direction of rotation after some delay.
- How to connect a capacitor → Page A-313

Accessories and Peripheral Equipment

Instantaneous Stop Brake Pack

→Page A-277



Accessories

→Page A-287



Induction Motors

6 W (1/125 HP)

Frame Size: □60 mm (□2.36 in.)



(Gearhead sold separately)

Specifications – Continuous Rating (RoHS)



Model Lead Wire Type		Output Power W HP	Voltage VAC	Frequency Hz	Current A	Starting Torque mN·m oz·in	Rated Torque mN·m oz·in	Rated Speed r/min	Capacitor μF
Pinion Shaft Type	Round Shaft Type								
Ⓜ 2IK6GN-AW2U	2IK6A-AW2U	6 1/125	Single-Phase 110	60	0.178	40	41	1450	2.5
			Single-Phase 115		0.182	5.6	5.8		
Ⓜ 2IK6GN-CW2E	2IK6A-CW2E	6 1/125	Single-Phase 220	50	0.103	38	49	1150	0.6
				60	0.091	5.6	5.8	1450	
			Single-Phase 230	50	0.107	45	49	1200	
				60	0.094	40	41	1450	
Ⓜ 2IK6GN-SW2	2IK6A-SW2	6 1/125	Three-Phase 200	50	0.081	49	49	1200	-
				60	0.072	41	41	1400	
			Three-Phase 220	60	0.076	41	41	1500	
			Three-Phase 230	60	0.079	41	41	1500	

- The **U** and **E** at the end of the model name indicate that the unit includes a capacitor. These letters are not listed on the motor nameplate. When the motor is approved under various safety standards, the model name on the nameplate is the approved model name. → Page G-2
- Details of safety standards → Page G-2
- Details of RoHS Directive → Page G-38
- Ⓜ: Impedance protected

Product Line

● Motor (RoHS)

Type	Model	
	Pinion Shaft Type	Round Shaft Type
Lead Wire	2IK6GN-AW2U	2IK6A-AW2U
	2IK6GN-CW2E	2IK6A-CW2E
	2IK6GN-SW2	2IK6A-SW2

The following items are included in each product.
 Motor, Capacitor*, Capacitor Cap*, Operating Manual
 * Only for single-phase motors

● Parallel Shaft Gearhead (Sold separately) (RoHS)

Gearhead Type		Gearhead Model	Gear Ratio
Parallel Shaft	Long Life, Low Noise GN-S Gearhead	2GN□SA	3, 3.6, 5, 6, 7.5, 9, 12.5, 15, 18, 25, 30, 36, 50, 60, 75, 90, 100, 120, 150, 180
		2GN10XS (Decimal Gearhead)	

- Enter the gear ratio in the box (□) within the model name.

The following items are included in each product.
 Gearhead, Mounting Screws, Operating Manual

- Following gearheads are also available. For details, please refer to website (<http://www.orientalmotor.com/>) or contact the nearest Oriental Motor sales office.

Gearhead Type		Gearhead Model	Gear Ratio
Parallel Shaft	(RoHS)	2GN□KA	3~180
	GN-K Gearhead	2GN10XK (Decimal Gearhead)	

- Enter the gear ratio in the box (□) within the model name.

Gearmotor – Torque Table

- Gearheads and decimal gearheads are sold separately.
- Enter the gear ratio in the box (□) within the gearhead model name.
- A colored background (□) indicates gear shaft rotation in the same direction as the motor shaft, while the others rotate in the opposite direction.
- The speed is calculated by dividing the motor's synchronous speed (50 Hz: 1500 r/min, 60 Hz: 1800 r/min) by the gear ratio. The actual speed is 2~20% less than the displayed value, depending on the load.
- To reduce the speed beyond the gear ratio in the table, attach a decimal gearhead (gear ratio 10:1) between the gearhead and the motor. In that case, the permissible torque is 3 N·m (26 lb-in).

◇ 50 Hz

Unit = Upper values: N·m/Lower values: lb-in

Model	Speed r/min	500	416	300	250	200	166	120	100	83	60	50	41	30	25	20	16	15	12.5	10	8.3
	Gear Ratio	3	3.6	5	6	7.5	9	12.5	15	18	25	30	36	50	60	75	90	100	120	150	180
2IK6GN-CW2E 2IK6GN-SW2	2GN□SA	0.12	0.14	0.20	0.24	0.30	0.36	0.50	0.60	0.71	0.89	1.1	1.3	1.6	1.9	2.4	2.9	3	3	3	3
		1.06	1.23	1.77	2.1	2.6	3.1	4.4	5.3	6.2	7.8	9.7	11.5	14.1	16.8	21	25	26	26	26	26

◇ 60 Hz

Unit = Upper values: N·m/Lower values: lb-in

Model	Speed r/min	600	500	360	300	240	200	144	120	100	72	60	50	36	30	24	20	18	15	12	10
	Gear Ratio	3	3.6	5	6	7.5	9	12.5	15	18	25	30	36	50	60	75	90	100	120	150	180
2IK6GN-AW2U 2IK6GN-CW2E 2IK6GN-SW2	2GN□SA	0.10	0.12	0.17	0.20	0.25	0.30	0.42	0.50	0.60	0.75	0.90	1.1	1.4	1.6	2.0	2.4	2.7	3	3	3
		0.88	1.06	1.50	1.77	2.2	2.6	3.7	4.4	5.3	6.6	7.9	9.7	12.3	14.1	17.7	21	23	26	26	26

Permissible Overhung Load and Permissible Thrust Load

Motor (Round shaft type) → Page A-16

Gearhead → Page A-16

Permissible Load Inertia J of Gearhead


→ Page A-17

Dimensions Unit = mm (in.)

● Mounting screws are included with gearheads. Dimensions for mounting screws → Page A-310

◇ Lead Wire Type


Mass: Motor 0.7 kg (1.54 lb.)
Gearhead 0.4 kg (0.88 lb.)



Motor Leads 300 mm (12 in.) Length
UL Style 3271, AWG20

Motor Model	Gearhead Model	Gear Ratio	L	DXF
2IK6GN-AW2U 2IK6GN-CW2E 2IK6GN-SW2	2GN□SA	3~18	30 (1.18)	A443AU
		25~180	40 (1.57)	A443BU

● Enter the gear ratio in the box (□) within the model name.




Detail Drawing of Protective Earth Terminal

◇ Shaft Section of Round Shaft Type

The motor's dimensions (excluding the shaft section) are the same as those of the pinion shaft types.

Motor Model	Mass	DXF
2IK6A-AW2U 2IK6A-CW2E 2IK6A-SW2	0.7 kg (1.54 lb.)	A444




◇ Decimal Gearhead

Can be connected to **GN** pinion shaft type.

2GN10XS


Mass: 0.2 kg (0.44 lb.)

DXF A003



◇ Capacitor

(Included with single-phase motors)




◇ Capacitor Dimensions Unit = mm (in.)

Model		Capacitor Model	A	B	C	Mass g (oz.)	Capacitor Cap
Pinion Shaft Type	Round Shaft Type						
2IK6GN-AW2U	2IK6A-AW2U	CH25FAUL2	31 (1.22)	17 (0.67)	27 (1.06)	21 (0.74)	Included
2IK6GN-CW2E	2IK6A-CW2E	CH06BFAUL	31 (1.22)	14.5 (0.57)	23.5 (0.93)	18 (0.64)	

Connection Diagrams

- The direction of motor rotation is as viewed from the shaft end of the motor. CW represents the clockwise direction, while CCW represents the counterclockwise direction.
- Connection diagrams are also valid for the equivalent round shaft type.






PE: Protective Earth

Note:

- Change the direction of single-phase motor rotation only after bringing the motor to a stop. If an attempt is made to change the direction of rotation while the motor is rotating, motor may ignore reversing command or change its direction of rotation after some delay.
- How to connect a capacitor → Page A-313

Accessories and Peripheral Equipment

<p>Instantaneous Stop Brake Pack →Page A-277</p> 	<p>Speed Control Speed Controller →Page B-156</p> 	<p>Accessories →Page A-287</p> 
---	--	---

Induction Motors

15 W (1/50 HP)

Frame Size: □70 mm (□2.76 in.)



(Gearhead sold separately)

Specifications – Continuous Rating (RoHS)



Model Lead Wire Type		Output Power W HP	Voltage VAC	Frequency Hz	Current A	Starting Torque mN·m oz-in	Rated Torque mN·m oz-in	Rated Speed r/min	Capacitor μF
Pinion Shaft Type	Round Shaft Type								
ⓉP 3IK15GN-AW2U	3IK15A-AW2U	15 1/50	Single-Phase 110	60	0.33	65	105	1450	4.5
			Single-Phase 115		0.34	9.2	14.9		
ⓉP 3IK15GN-CW2E	3IK15A-CW2E	15 1/50	Single-Phase 220	50	0.19	70 9.9	125 17.7	1200	1.0
				60	0.16	65 9.2	105 14.9		
			Single-Phase 230	50	0.19	75 10.6	125 17.7	1200	
				60	0.16	65 9.2	105 14.9		

- The **U** and **E** at the end of the model name indicate that the unit includes a capacitor. These letters are not listed on the motor nameplate. When the motor is approved under various safety standards, the model name on the nameplate is the approved model name. → Page G-11
- Details of safety standards → Page G-2
- Details of RoHS Directive → Page G-38

ⓉP: Contains a built-in thermal protector (automatic return type). If a motor overheats for any reason, the thermal protector is activated and the motor is stopped. When the motor temperature drops, the thermal protector closes and the motor restarts. Be sure to turn the motor power off before inspecting.

Product Line

● Motor (RoHS)

Type	Model	
	Pinion Shaft Type	Round Shaft Type
Lead Wire	3IK15GN-AW2U	3IK15A-AW2U
	3IK15GN-CW2E	3IK15A-CW2E

The following items are included in each product.
Motor, Capacitor, Capacitor Cap, Operating Manual

● Parallel Shaft Gearhead (Sold separately) (RoHS)

Gearhead Type		Gearhead Model	Gear Ratio
Parallel Shaft	Long Life, Low Noise GN-S Gearhead	3GN□SA	3, 3.6, 5, 6, 7.5, 9, 12.5, 15, 18, 25, 30, 36, 50, 60, 75, 90, 100, 120, 150, 180
		3GN10XS (Decimal Gearhead)	

- Enter the gear ratio in the box (□) within the model name.

The following items are included in each product.
Gearhead, Mounting Screws, Operating Manual

- Following gearheads are also available. For details, please refer to website (<http://www.orientalmotor.com/>) or contact the nearest Oriental Motor sales office.

Gearhead Type		Gearhead Model	Gear Ratio
Parallel Shaft	(RoHS)	3GN□KA	3~180
	GN-K Gearhead	3GN10XK (Decimal Gearhead)	

- Enter the gear ratio in the box (□) within the model name.

Gearmotor – Torque Table

- Gearheads and decimal gearheads are sold separately.
- Enter the gear ratio in the box (□) within the gearhead model name.
- A colored background (□) indicates gear shaft rotation in the same direction as the motor shaft, while the others rotate in the opposite direction.
- The speed is calculated by dividing the motor's synchronous speed (50 Hz: 1500 r/min, 60 Hz: 1800 r/min) by the gear ratio. The actual speed is 2~20% less than the displayed value, depending on the load.
- To reduce the speed beyond the gear ratio in the table, attach a decimal gearhead (gear ratio 10:1) between the gearhead and the motor. In that case, the permissible torque is 5 N·m (44 lb-in).

◇ 50 Hz

Unit = Upper values: N-m/Lower values: lb-in

Model	Speed r/min	500	416	300	250	200	166	120	100	83	60	50	41	30	25	20	16	15	12.5	10	8.3
		Gear Ratio	3	3.6	5	6	7.5	9	12.5	15	18	25	30	36	50	60	75	90	100	120	150
3IK15GN-CW2E	3GN□SA	0.30	0.36	0.51	0.61	0.76	0.91	1.3	1.5	1.8	2.3	2.7	3.3	4.1	5	5	5	5	5	5	5
		2.6	3.1	4.5	5.3	6.7	8.0	11.5	13.2	15.9	20	23	29	36	44	44	44	44	44	44	44

◇ 60 Hz

Unit = Upper values: N-m/Lower values: lb-in

Model	Speed r/min	600	500	360	300	240	200	144	120	100	72	60	50	36	30	24	20	18	15	12	10
		Gear Ratio	3	3.6	5	6	7.5	9	12.5	15	18	25	30	36	50	60	75	90	100	120	150
3IK15GN-AW2U 3IK15GN-CW2E	3GN□SA	0.26	0.31	0.43	0.51	0.64	0.77	1.1	1.3	1.5	1.9	2.3	2.8	3.5	4.2	5	5	5	5	5	5
		2.3	2.7	3.8	4.5	5.6	6.8	9.7	11.5	13.2	16.8	20	24	30	37	44	44	44	44	44	44

Permissible Overhung Load and Permissible Thrust Load

Motor (Round shaft type) → Page A-16

Gearhead → Page A-16

Permissible Load Inertia J of Gearhead

→ Page A-17

Dimensions Unit = mm (in.)

- Mounting screws are included with gearheads. Dimensions for mounting screws → Page A-310



◇ Lead Wire Type

Mass: Motor 1.1 kg (2.4 lb.)

Gearhead 0.55 kg (1.21 lb.)

Motor Model	Gearhead Model	Gear Ratio	L	DXF
3IK15GN-AW2U 3IK15GN-CW2E	3GN□SA	3~18	32 (1.26)	A447AU
		25~180	42 (1.65)	A447BU

- Enter the gear ratio in the box (□) within the model name.




Detail Drawing of Protective Earth Terminal

◇ Shaft Section of Round Shaft Type

The motor's dimensions (excluding the shaft section) are the same as those of the pinion shaft types.

Motor Model	Mass	DXF
3IK15A-AW2U 3IK15A-CW2E	1.1 kg (2.4 lb.)	A448




◇ Decimal Gearhead

Can be connected to **GN** pinion shaft type.


3GN10XS

Mass: 0.3 kg (0.66 lb.)

DXF A009




◇ Capacitor (Included)




◇ Capacitor Dimensions Unit = mm (in.)

Model		Capacitor Model	A	B	C	Mass g (oz.)	Capacitor Cap
Pinion Shaft Type	Round Shaft Type						
3IK15GN-AW2U	3IK15A-AW2U	CH45FAUL2	37 (1.46)	18 (0.71)	27 (1.06)	26 (0.92)	Included
3IK15GN-CW2E	3IK15A-CW2E	CH10BFAUL	37 (1.46)	18 (0.71)	27 (1.06)	27 (0.95)	



■ Connection Diagrams

- The direction of motor rotation is as viewed from the shaft end of the motor. CW represents the clockwise direction, while CCW represents the counterclockwise direction.
- Connection diagrams are also valid for the equivalent round shaft type.



PE: Protective Earth

Note:

- Change the direction of single-phase motor rotation only after bringing the motor to a stop. If an attempt is made to change the direction of rotation while the motor is rotating, motor may ignore reversing command or change its direction of rotation after some delay.
- How to connect a capacitor → Page A-313

Accessories and Peripheral Equipment

- Instantaneous Stop Brake Pack → Page A-277
- Accessories → Page A-287



Induction Motors

25 W (1/30 HP)

Frame Size: □80 mm (□3.15 in.)



Lead Wire Type



Terminal Box Type

(Gearhead sold separately)

Specifications – Continuous Rating (RoHS)



Model Upper Model Name: Pinion Shaft Type Lower Model Name (): Round Shaft Type			Output Power	Voltage	Frequency	Current	Starting Torque	Rated Torque	Rated Speed	Capacitor
Lead Wire Type Dimension ①	Terminal Box Type Dimension ②	Conduit Box Type Dimension ③	W HP	VAC	Hz	A	mN-m oz-in	mN-m oz-in	r/min	μF
TP 4IK25GN-AW2U (4IK25A-AW2U)	4IK25GN-AW2TU (4IK25A-AW2TU)	4IK25GN-FCH (4IK25AA-FCH)	25 1/30	Single-Phase 110 Single-Phase 115	60	0.46	120 17.0	170 24	1450	6.5
TP 4IK25GN-CW2E (4IK25A-CW2E)	4IK25GN-CW2TE (4IK25A-CW2TE)	-	25 1/30	Single-Phase 220	50	0.27	110 15.6	205 29	1200	1.5
					60	0.23		170 24	1450	
				Single-Phase 230	50	0.27	120 17.0	205 29	1200	
					60	0.23		170 24	1450	
TP -	-	4IK25GN-ECH (4IK25AA-ECH)	25 1/30	Single-Phase 220	60	0.22	120 17.0	170 24	1450	1.5
				Single-Phase 230	50	0.24		205 29	1200	
					60	0.22		170 24	1450	
TP 4IK25GN-SW2 (4IK25A-SW2)	4IK25GN-SW2T (4IK25A-SW2T)	4IK25GN-SH (4IK25AA-SH)	25 1/30	Three-Phase 200	50	0.23	240 34	190 26	1300	-
				Three-Phase 220	60	0.21	160 22	160 22	1550	
					Three-Phase 230	60	0.21	160 22	160 22	

● The **U** and **E** at the end of the model name indicate that the unit includes a capacitor. These letters are not listed on the motor nameplate.

When the motor is approved under various safety standards, the model name on the nameplate is the approved model name. → Page G-11

● Details of safety standards → Page G-2

● Details of RoHS Directive → Page G-38

* Conduit box type is not certified under the China Compulsory Certification System (CCC System).

Ⓧ: Contains a built-in thermal protector (automatic return type). If a motor overheats for any reason, the thermal protector is activated and the motor is stopped. When the motor temperature drops, the thermal protector closes and the motor restarts. Be sure to turn the motor power off before inspecting.

Product Line

● Motor (RoHS)

Type	Model	
	Pinion Shaft Type	Round Shaft Type
Lead Wire	4IK25GN-AW2U	4IK25A-AW2U
	4IK25GN-CW2E	4IK25A-CW2E
	4IK25GN-SW2	4IK25A-SW2
Terminal Box	4IK25GN-AW2TU	4IK25A-AW2TU
	4IK25GN-CW2TE	4IK25A-CW2TE
	4IK25GN-SW2T	4IK25A-SW2T
Conduit Box	4IK25GN-FCH	4IK25AA-FCH
	4IK25GN-ECH	4IK25AA-ECH
	4IK25GN-SH	4IK25AA-SH

The following items are included in each product.

Motor, Capacitor*, Capacitor Cap*, Operating Manual

* Only for single-phase motors (Excluding conduit box type)

● **Parallel Shaft Gearhead/Right-Angle Gearhead**
(Sold separately) **(RoHS)**

Gearhead Type		Gearhead Model	Gear Ratio
Parallel Shaft	Long Life, Low Noise GN-S Gearhead	4GN□SA	3, 3.6, 5, 6, 7.5, 9, 12.5, 15, 18, 25, 30, 36, 50, 60, 75, 90, 100, 120, 150, 180
	Hollow Shaft	4GN□RH	
Right-Angle Shaft	Solid Shaft	4GN□RAA	
Parallel Shaft	Long Life, Low Noise GN-S Gearhead	4GN10XS (Decimal Gearhead)	

● Enter the gear ratio in the box (□) within the model name.

- The following items are included in each product.
- Parallel Shaft Gearhead
Gearhead, Mounting Screws, Operating Manual
 - Hollow Shaft Gearhead
Gearhead, Mounting Screws, Parallel Key, Safety Cover (with screws), Gasket, Operating Manual
 - Solid Shaft Gearhead
Gearhead, Mounting Screws, Gasket, Operating Manual

● Following gearheads are also available. For details, please refer to website (<http://www.orientalmotor.com/>) or contact the nearest Oriental Motor sales office.

Gearhead Type		Gearhead Model	Gear Ratio
Parallel Shaft	(RoHS) GN-K Gearhead	4GN□KA	3~180
		4GN10XK (Decimal Gearhead)	

● Enter the gear ratio in the box (□) within the model name.

■ **Gearmotor – Torque Table**

- Gearheads and decimal gearheads are sold separately.
- Enter the code that represents the terminal box type "T" in the box (□) within the motor model name.
- Enter the gear ratio in the box (□) within the gearhead model name.
- A colored background (□) indicates gear shaft rotation in the same direction as the motor shaft, while the others rotate in the opposite direction.
- The speed is calculated by dividing the motor's synchronous speed (50 Hz: 1500 r/min, 60 Hz: 1800 r/min) by the gear ratio.
The actual speed is 2~20% less than the displayed value, depending on the load.
- To reduce the speed beyond the gear ratio in the table, attach a decimal gearhead (gear ratio 10:1) between the gearhead and the motor.
In that case, the permissible torque is 8 N·m (70 lb-in). When a gearhead of 25:1~36:1 is connected, the value for permissible torque is 6 N·m (53 lb-in).

◇ **50 Hz**

Unit = Upper values: N·m/ Lower values: lb-in

Model Motor/ Gearhead	Speed r/min	500	416	300	250	200	166	120	100	83	60	50	41	30	25	20	16	15	12.5	10	8.3
	Gear Ratio	3	3.6	5	6	7.5	9	12.5	15	18	25	30	36	50	60	75	90	100	120	150	180
4IK25GN-CW2□E 4IK25GN-ECH	4GN□SA	0.50 4.4	0.60 5.3	0.83 7.3	1.0 8.8	1.2 10.6	1.5 13.2	2.1 18.5	2.5 22	3.0 26	3.7 32	4.5 39	5.4 47	6.8 60	8 70	8 70	8 70	8 70	8 70	8 70	8 70
4IK25GN-SW2□ 4IK25GN-SH	4GN□SA	0.46 4.0	0.55 4.8	0.77 6.8	0.92 8.1	1.2 10.6	1.4 12.3	1.9 16.8	2.3 20	2.8 24	3.5 30	4.2 37	5.0 44	6.3 55	7.5 66	8 70	8 70	8 70	8 70	8 70	8 70

◇ **60 Hz**

Unit = Upper values: N·m/ Lower values: lb-in

Model Motor/ Gearhead	Speed r/min	600	500	360	300	240	200	144	120	100	72	60	50	36	30	24	20	18	15	12	10
	Gear Ratio	3	3.6	5	6	7.5	9	12.5	15	18	25	30	36	50	60	75	90	100	120	150	180
4IK25GN-AW2□U 4IK25GN-CW2□E 4IK25GN-FCH 4IK25GN-ECH	4GN□SA	0.41 3.6	0.50 4.4	0.69 6.1	0.83 7.3	1.0 8.8	1.2 10.6	1.7 15.0	2.1 18.5	2.5 22	3.1 27	3.7 32	4.5 39	5.6 49	6.7 59	8 70	8 70	8 70	8 70	8 70	8 70
4IK25GN-SW2□ 4IK25GN-SH	4GN□SA	0.39 3.4	0.47 4.1	0.65 5.7	0.78 6.9	0.97 8.5	1.2 10.6	1.6 14.1	1.9 16.8	2.3 20	2.9 25	3.5 30	4.2 37	5.3 46	6.3 55	7.9 69	8 70	8 70	8 70	8 70	8 70

■ **Gearmotor – Torque Table When Right-Angle Gearhead is Attached**

→ Page A-248

■ **Permissible Overhung Load and Permissible Thrust Load**

Motor (Round shaft type) → Page A-16
Gearhead → Page A-16

■ **Permissible Load Inertia J of Gearhead**

→ Page A-17


Introduction
Induction Motors
Reversible Motors
Electro-magnetic Brake Motors
V Series
Clutch & Brake Motors
Synchronous Motors
Low-Speed Synchronous Motors
Waterlight, Dust-Resistant Motors
Torque Motors
Right-Angle Gearheads
Linear Heads
Brake Pack
Accessories
Installation

Dimensions Unit = mm (in.)

● Mounting screws are included with gearheads. Dimensions for mounting screws → Page A-310


◇ Lead Wire Type ①

Mass: Motor 1.5 kg (3.3 lb.)
Gearhead 0.65 kg (1.43 lb.)



Motor Model	Gearhead Model	Gear Ratio	L	DXF
4IK25GN-AW2U 4IK25GN-CW2E 4IK25GN-SW2	4GN□SA	3~18	32 (1.26)	A449AU
		25~180	42.5 (1.67)	A449BU


● Enter the gear ratio in the box (□) within the model name.



Detail Drawing of Protective Earth Terminal

◇ Terminal Box Type ②

Mass: Motor 1.7 kg (3.7 lb.)
Gearhead 0.65 kg (1.43 lb.)




Motor Model	Gearhead Model	Gear Ratio	L	DXF
4IK25GN-AW2TU 4IK25GN-CW2TE 4IK25GN-SW2T	4GN□SA	3~18	32 (1.26)	A451AU
		25~180	42.5 (1.67)	A451BU

● Enter the gear ratio in the box (□) within the model name.

- Use cable with a diameter of $\phi 6 \sim \phi 12$ mm ($\phi 0.24 \sim \phi 0.47$ in.).
- Details of terminal box → Page A-314

◇ Shaft Section of Round Shaft Type

The motor's dimensions (excluding the shaft section) are the same as those of the pinion shaft types.




Motor Model	Mass	DXF
4IK25A-AW2U 4IK25A-CW2E 4IK25A-SW2	1.5 kg (3.3 lb.)	A450
4IK25A-AW2TU 4IK25A-CW2TE 4IK25A-SW2T	1.7 kg (3.7 lb.)	A328

◇ Conduit Box Type ③

Motor Model	Gearhead Model	Gear Ratio	L	DXF
4IK25GN-FCH	4GN□SA	3~18	32 (1.26)	A900AU
4IK25GN-ECH		25~180	42.5 (1.67)	A900BU

● Enter the gear ratio in the box (□) within the model name.

Mass: Motor 1.9 kg (4.2 lb.)
Gearhead 0.65 kg (1.43 lb.)




3 Motor Leads: UL Style 3266, AWG20
1 Ground Lead: UL Style 3266, AWG18
● Details of terminal box → Page A-314

Motor Model	Gearhead Model	Gear Ratio	L	DXF
4IK25GN-SH	4GN□SA	3~18	32 (1.26)	A901AU
		25~180	42.5 (1.67)	A901BU

● Enter the gear ratio in the box (□) within the model name.

Mass: Motor 1.7 kg (3.7 lb.)
Gearhead 0.65 kg (1.43 lb.)



3 Motor Leads: UL Style 3266, AWG20
1 Ground Lead: UL Style 3266, AWG18
● Details of terminal box → Page A-314

◇ Shaft Section of Round Shaft Type



The motor's dimensions (excluding the shaft section) are the same as those of the pinion shaft types.

Motor Model	Mass	DXF
4IK25AA-FCH	1.9 kg (4.2 lb.)	A809
4IK25AA-ECH		

◇ Shaft Section of Round Shaft Type

The motor's dimensions (excluding the shaft section) are the same as those of the pinion shaft types.

Motor Model	Mass	DXF
4IK25AA-SH	1.7 kg (3.7 lb.)	A810




◇ Decimal Gearhead

Can be connected to **GN** pinion shaft type.

4GN10XS


Mass: 0.4 kg (0.88 lb.)

DXF A013



◇ Capacitor

(Included with single-phase motors)



◇ Capacitor Dimensions Unit = mm (in.)

Model		Capacitor Model	A	B	C	Mass g (oz.)	Capacitor Cap
Upper Model Name: Pinion Shaft Type	Lower Model Name (): Round Shaft Type						
Lead Wire Type	Terminal Box Type						
4IK25GN-AW2U (4IK25A-AW2U)	4IK25GN-AW2TU (4IK25A-AW2TU)	CH65CFAUL2	48 (1.89)	19 (0.75)	29 (1.14)	35 (1.24)	Included
4IK25GN-CW2E (4IK25A-CW2E)	4IK25GN-CW2TE (4IK25A-CW2TE)	CH15BFAUL	38 (1.50)	21 (0.83)	31 (1.22)	37 (1.31)	

■ Connection Diagrams


- The direction of motor rotation is as viewed from the shaft end of the motor. CW represents the clockwise direction, while CCW represents the counterclockwise direction.
- Connection diagrams are also valid for the equivalent round shaft type.

Lead Wire Type		Terminal Box Type	
4IK25GN-AW2U 4IK25GN-CW2E	4IK25GN-SW2	4IK25GN-AW2TU 4IK25GN-CW2TE	4IK25GN-SW2T
<p>Clockwise</p>	<p>Clockwise</p>	<p>Clockwise</p>	<p>Clockwise</p>
<p>Counterclockwise</p>	<p>Counterclockwise</p> <p>To change the rotation direction, change any two connections between L1(R), L2(S) and L3(T).</p>	<p>Counterclockwise</p>	<p>Counterclockwise</p> <p>To change the rotation direction, change any two connections between L1(R), L2(S) and L3(T).</p>

PE: Protective Earth

Note:

- Change the direction of single-phase motor rotation only after bringing the motor to a stop. If an attempt is made to change the direction of rotation while the motor is rotating, motor may ignore reversing command or change its direction of rotation after some delay.
- How to connect a capacitor → Page A-313



PE: Protective Earth

Note:

- Change the direction of single-phase motor rotation only after bringing the motor to a stop.
If an attempt is made to change the direction of rotation while the motor is rotating, motor may ignore reversing command or change its direction of rotation after some delay.
- How to connect a capacitor → Page A-313

Gearhead, Accessories and Peripheral Equipment

<p>Space-Saving Right-Angle Gearheads → Page A-239</p>	<p>Instantaneous Stop Brake Pack → Page A-277</p>	<p>Speed Control Speed Controller → Page B-156</p>	<p>Accessories → Page A-287</p>
---	--	---	--

Induction Motors

40 W (1/19 HP)

Frame Size: □90 mm (□3.54 in.)



Lead Wire Type



Terminal Box Type

(Gearhead sold separately)

Specifications – Continuous Rating (RoHS)



Model			Output Power	Voltage	Frequency	Current	Starting Torque	Rated Torque	Rated Speed	Capacitor
Upper Model Name: Pinion Shaft Type Lower Model Name (): Round Shaft Type										
Lead Wire Type Dimension ①	Terminal Box Type Dimension ②	Conduit Box Type Dimension ③	W HP	VAC	Hz	A	mN·m oz·in	mN·m oz·in	r/min	μF
ⓉP 5IK40GN-AW2U (5IK40A-AW2U)	5IK40GN-AW2TU (5IK40A-AW2TU)	5IK40GN-FCH (5IK40AA-FCH)	40 1/19	Single-Phase 110	60	0.68	200 28	260 36	1500	9.0
				Single-Phase 115		0.67				
ⓉP 5IK40GN-CW2E (5IK40A-CW2E)	5IK40GN-CW2TE (5IK40A-CW2TE)	5IK40GN-ECH*1 (5IK40AA-ECH)*1	40 1/19	Single-Phase 220	50	0.39	200 28	315 44	1250	2.3
					60	0.35		260 36		
				Single-Phase 230	50	0.39	200 28	300 42	1300	
					60	0.34		260 36	1500	
ⓉP 5IK40GN-SW2 (5IK40A-SW2)	5IK40GN-SW2T (5IK40A-SW2T)	5IK40GN-SH (5IK40AA-SH)	40 1/19	Three-Phase 200	50	0.32	400 56	300 42	1300	-
					60	0.30	260 36	260 36	1550	
				Three-Phase 220	60	0.30	260 36	260 36	1600	
				Three-Phase 230	60	0.31	260 36	260 36	1600	

● The **U** and **E** at the end of the model name indicate that the unit includes a capacitor. These letters are not listed on the motor nameplate.

When the motor is approved under various safety standards, the model name on the nameplate is the approved model name. → Page G-11

● Details of safety standards → Page G-2 ● Details of RoHS Directive → Page G-38

*1 Single-Phase 220 VAC 50Hz type is not available for conduit box type.

*2 Conduit box type is not certified under the China Compulsory Certification System (CCC System).

ⓉP: Contains a built-in thermal protector (automatic return type). If a motor overheats for any reason, the thermal protector is activated and the motor is stopped. When the motor temperature drops, the thermal protector closes and the motor restarts. Be sure to turn the motor power off before inspecting.

Product Line

● Motor (RoHS)

Type	Model	
	Pinion Shaft Type	Round Shaft Type
Lead Wire	5IK40GN-AW2U	5IK40A-AW2U
	5IK40GN-CW2E	5IK40A-CW2E
	5IK40GN-SW2	5IK40A-SW2
Terminal Box	5IK40GN-AW2TU	5IK40A-AW2TU
	5IK40GN-CW2TE	5IK40A-CW2TE
	5IK40GN-SW2T	5IK40A-SW2T
Conduit Box	5IK40GN-FCH	5IK40AA-FCH
	5IK40GN-ECH	5IK40AA-ECH
	5IK40GN-SH	5IK40AA-SH

The following items are included in each product.

Motor, Capacitor*, Capacitor Cap*, Operating Manual

* Only for single-phase motors (Excluding conduit box type)

● Parallel Shaft Gearhead/Right-Angle Gearhead (Sold separately) (RoHS)

Gearhead Type		Gearhead Model	Gear Ratio
Parallel Shaft	Long Life, Low Noise GN-S Gearhead	5GN□SA	3, 3.6, 5, 6, 7.5, 9, 12.5, 15, 18, 25, 30, 36, 50, 60, 75, 90, 100, 120, 150, 180
Right-Angle Shaft	Hollow Shaft	5GN□RH	
	Solid Shaft	5GN□RAA	
Parallel Shaft	Long Life, Low Noise GN-S Gearhead	5GN10XS (Decimal Gearhead)	

● Enter the gear ratio in the box (□) within the model name.

The following items are included in each product.

- Parallel Shaft Gearhead
Gearhead, Mounting Screws, Operating Manual
- Hollow Shaft Gearhead
Gearhead, Mounting Screws, Parallel Key, Safety Cover (with screws), Gasket, Operating Manual
- Solid Shaft Gearhead
Gearhead, Mounting Screws, Gasket, Operating Manual

● Following gearheads are also available. For details, please refer to website (<http://www.orientalmotor.com/>) or contact the nearest Oriental Motor sales office.

Gearhead Type		Gearhead Model	Gear Ratio
Parallel Shaft	(RoHS) GN-K Gearhead	5GN□KA	3~180
		5GN10XK (Decimal Gearhead)	

● Enter the gear ratio in the box (□) within the model name.

Gearmotor – Torque Table

- Gearheads and decimal gearheads are sold separately.
- Enter the code that represents the terminal box type "T" in the box (□) within the motor model name.
- Enter the gear ratio in the box (□) within the gearhead model name.
- A colored background (□) indicates gear shaft rotation in the same direction as the motor shaft, while the others rotate in the opposite direction.
- The speed is calculated by dividing the motor's synchronous speed (50 Hz: 1500 r/min, 60 Hz: 1800 r/min) by the gear ratio. The actual speed is 2~20% less than the displayed value, depending on the load.
- To reduce the speed beyond the gear ratio in the table, attach a decimal gearhead (gear ratio 10:1) between the gearhead and the motor. In that case, the permissible torque is 10 N·m (88 lb-in).

◇ 50 Hz

Unit = Upper values: N·m/Lower values: lb-in

Model Motor/ Gearhead	Speed r/min	500	416	300	250	200	166	120	100	83	60	50	41	30	25	20	16	15	12.5	10	8.3
	Gear Ratio	3	3.6	5	6	7.5	9	12.5	15	18	25	30	36	50	60	75	90	100	120	150	180
5IK40GN-CW2 □□E (Single-phase 220 VAC)	5GN □SA	0.77	0.92	1.3	1.5	1.9	2.3	3.2	3.8	4.6	5.7	6.9	8.3	10	10	10	10	10	10	10	10
		6.8	8.1	11.5	13.2	16.8	20	28	33	40	50	61	73	88	88	88	88	88	88	88	88
5IK40GN-CW2 □□E 5IK40GN-ECH (Single-phase 230 VAC) 5IK40GN-SW2 □□ 5IK40GN-SH	5GN □SA	0.73	0.87	1.2	1.5	1.8	2.2	3.0	3.6	4.4	5.5	6.6	7.9	9.9	10	10	10	10	10	10	10
		6.4	7.6	10.6	13.2	15.9	19.4	26	31	38	48	58	69	87	88	88	88	88	88	88	88

◇ 60 Hz

Unit = Upper values: N·m/Lower values: lb-in

Model Motor/ Gearhead	Speed r/min	600	500	360	300	240	200	144	120	100	72	60	50	36	30	24	20	18	15	12	10
	Gear Ratio	3	3.6	5	6	7.5	9	12.5	15	18	25	30	36	50	60	75	90	100	120	150	180
5IK40GN-AW2 □□U 5IK40GN-CW2 □□E 5IK40GN-SW2 □□ 5IK40GN-FCH 5IK40GN-ECH 5IK40GN-SH	5GN □SA	0.63	0.76	1.1	1.3	1.6	1.9	2.6	3.2	3.8	4.7	5.7	6.8	8.6	10	10	10	10	10	10	10
		5.5	6.7	9.7	11.5	14.1	16.8	23	28	33	41	50	60	76	88	88	88	88	88	88	88

Gearmotor – Torque Table When Right-Angle Gearhead is Attached

→ Page A-248

Permissible Overhung Load and Permissible Thrust Load

Motor (Round shaft type) → Page A-16

Gearhead → Page A-16

Permissible Load Inertia J of Gearhead

→ Page A-17


Dimensions Unit = mm (in.)

- Mounting screws are included with gearheads. Dimensions for mounting screws → Page A-310

◇ Lead Wire Type ①


Mass: Motor 2.5 kg (5.5 lb.)

Gearhead 1.5 kg (3.3 lb.)



Motor Model	Gearhead Model	Gear Ratio	L	DXF
5IK40GN-AW2U 5IK40GN-CW2E 5IK40GN-SW2	5GN □SA	3~18	42 (1.65)	A452AU
		25~180	60 (2.36)	A452BU

- Enter the gear ratio in the box (□) within the model name.




◇ Conduit Box Type ③

Motor Model	Gearhead Model	Gear Ratio	L	DXF
5IK40GN-FCH	5GN□SA	3~18	42 (1.65)	A902AU
5IK40GN-ECH		25~180	60 (2.36)	A902BU

● Enter the gear ratio in the box (□) within the model name.

Mass: Motor 2.7 kg (5.9 lb.)
Gearhead 1.5 kg (3.3 lb.)




3 Motor Leads: UL Style 3266, AWG20
1 Ground Lead: UL Style 3266, AWG18
● Details of terminal box → Page A-314

Motor Model	Gearhead Model	Gear Ratio	L	DXF
5IK40GN-SH	5GN□SA	3~18	42 (1.65)	A903AU
		25~180	60 (2.36)	A903BU

● Enter the gear ratio in the box (□) within the model name.

Mass: Motor 2.5 kg (5.5 lb.)
Gearhead 1.5 kg (3.3 lb.)




3 Motor Leads: UL Style 3266, AWG20
1 Ground Lead: UL Style 3266, AWG18
● Details of terminal box → Page A-314

◇ Shaft Section of Round Shaft Type

The motor's dimensions (excluding the shaft section) are the same as those of the pinion shaft types.


Motor Model	Mass	DXF
5IK40AA-FCH	2.7 kg (5.9 lb.)	A811
5IK40AA-ECH		



◇ Shaft Section of Round Shaft Type

The motor's dimensions (excluding the shaft section) are the same as those of the pinion shaft types.

Motor Model	Mass	DXF
5IK40AA-SH	2.5 kg (5.5 lb.)	A812




◇ Decimal Gearhead

Can be connected to **GN** pinion shaft type.

5GN10XS


Mass: 0.6 kg (1.32 lb.)

DXF A022



◇ Capacitor

(Included with single-phase motors)



◇ Capacitor Dimensions Unit = mm (in.)

Model		Capacitor Model	A	B	C	Mass g (oz.)	Capacitor Cap
Upper Model Name: Pinion Shaft Type	Lower Model Name (): Round Shaft Type						
Lead Wire Type	Terminal Box Type						
5IK40GN-AW2U (5IK40A-AW2U)	5IK40GN-AW2TU (5IK40A-AW2TU)	CH90CFAUL2	48 (1.89)	22.5 (0.89)	31.5 (1.24)	45 (1.59)	Included
5IK40GN-CW2E (5IK40A-CW2E)	5IK40GN-CW2TE (5IK40A-CW2TE)	CH23BFAUL	48 (1.89)	21 (0.83)	31 (1.22)	43 (1.52)	

■ Connection Diagrams

- The direction of motor rotation is as viewed from the shaft end of the motor. CW represents the clockwise direction, while CCW represents the counterclockwise direction.
- Connection diagrams are also valid for the equivalent round shaft type.


Lead Wire Type		Terminal Box Type	
5IK40GN-AW2U 5IK40GN-CW2E	5IK40GN-SW2	5IK40GN-AW2TU 5IK40GN-CW2TE	5IK40GN-SW2T
<p>Clockwise</p>	<p>Clockwise</p>	<p>Clockwise</p>	<p>Clockwise</p>
<p>Counterclockwise</p>	<p>Counterclockwise</p> <p>To change the rotation direction, change any two connections between L1(R), L2(S) and L3(T).</p>	<p>Counterclockwise</p>	<p>Counterclockwise</p> <p>To change the rotation direction, change any two connections between L1(R), L2(S) and L3(T).</p>

PE: Protective Earth

Note:

- Change the direction of single-phase motor rotation only after bringing the motor to a stop. If an attempt is made to change the direction of rotation while the motor is rotating, motor may ignore reversing command or change its direction of rotation after some delay.

● How to connect a capacitor → Page A-313



PE: Protective Earth

Note:

- Change the direction of single-phase motor rotation only after bringing the motor to a stop. If an attempt is made to change the direction of rotation while the motor is rotating, motor may ignore reversing command or change its direction of rotation after some delay.
- How to connect a capacitor → Page A-313


Gearhead, Accessories and Peripheral Equipment

<p>Space-Saving Right-Angle Gearheads → Page A-239</p>	<p>Instantaneous Stop Brake Pack → Page A-277</p>	<p>Speed Control Speed Controller → Page B-156</p>	<p>Accessories → Page A-287</p>
---	--	---	--

Induction Motors

60 W (1/12 HP)

Frame Size: □90 mm (□3.54 in.)



Lead Wire Type

Terminal Box Type

(Gearhead sold separately)

Specifications – Continuous Rating (RoHS)



Model			Output Power	Voltage	Frequency	Current	Starting Torque	Rated Torque	Rated Speed	Capacitor
Upper Model Name: Pinion Shaft Type Lower Model Name (): Round Shaft Type										
Lead Wire Type Dimension ①	Terminal Box Type Dimension ②	Conduit Box Type Dimension ③	W HP	VAC	Hz	A	mN-m oz-in	mN-m oz-in	r/min	μF
TP 5IK60GE-AW2U (5IK60A-AW2U)	5IK60GE-AW2TU (5IK60A-AW2TU)	5IK60GE-FCH (5IK60A-FCH)	60 1/12	Single-Phase 110	60	1.09	320	405	1450	18
				Single-Phase 115		1.10				
TP 5IK60GE-CW2E (5IK60A-CW2E)	5IK60GE-CW2TE (5IK60A-CW2TE)	5IK60GE-ECH* ¹ (5IK60A-ECH)* ¹	60 1/12	Single-Phase 220	50	0.55	320 45	490	1200	4.0
					60	0.54		69		
				Single-Phase 230	50	0.57		57	1450	
					60	0.54		490	1200	
TP 5IK60GE-SW2 (5IK60A-SW2)	5IK60GE-SW2T (5IK60A-SW2T)	5IK60GE-SH (5IK60A-SH)	60 1/12	Three-Phase 200	50	0.50	600	450	1300	-
					60	0.43	85	63		
				Three-Phase 220	60	0.45	500	380	1550	
				Three-Phase 230	60	0.46	500	380	1600	
							71	53	1600	

● The **U** and **E** at the end of the model name indicate that the unit includes a capacitor. These letters are not listed on the motor nameplate. When the motor is approved under various safety standards, the model name on the nameplate is the approved model name. → Page G-11

● Details of safety standards → Page G-2

● Details of RoHS Directive → Page G-38

*1 Single-Phase 220 VAC 50Hz type is not available for conduit box type.

*2 Conduit box type is not certified under the China Compulsory Certification System (CCC System).

TP: Contains a built-in thermal protector (automatic return type). If a motor overheats for any reason, the thermal protector is activated and the motor is stopped. When the motor temperature drops, the thermal protector closes and the motor restarts. Be sure to turn the motor power off before inspecting.

Product Line

● Motor (RoHS)

Type	Model	
	Pinion Shaft Type	Round Shaft Type
Lead Wire	5IK60GE-AW2U	5IK60A-AW2U
	5IK60GE-CW2E	5IK60A-CW2E
	5IK60GE-SW2	5IK60A-SW2
Terminal Box	5IK60GE-AW2TU	5IK60A-AW2TU
	5IK60GE-CW2TE	5IK60A-CW2TE
	5IK60GE-SW2T	5IK60A-SW2T
Conduit Box	5IK60GE-FCH	5IK60A-FCH
	5IK60GE-ECH	5IK60A-ECH
	5IK60GE-SH	5IK60A-SH

The following items are included in each product.
 Motor, Capacitor*, Capacitor Cap*, Operating Manual
 * Only for single-phase motors (Excluding conduit box type)

● Parallel Shaft Gearhead/Right-Angle Gearhead (Sold separately) (RoHS)

Gearhead Type		Gearhead Model	Gear Ratio
Parallel Shaft	Long Life GE-S Gearhead	5GE□SA	3, 3.6, 5, 6, 7.5, 9, 12.5, 15, 18, 25, 30, 36, 50, 60, 75, 90, 100, 120, 150, 180
	Right-Angle Shaft	Hollow Shaft	
		Solid Shaft	
Parallel Shaft	Long Life GE-S Gearhead	5GE10XS (Decimal Gearhead)	

● Enter the gear ratio in the box (□) within the model name.

The following items are included in each product.

- Parallel Shaft Gearhead
Gearhead, Mounting Screws, Parallel Key, Operating Manual
- Hollow Shaft Gearhead
Gearhead, Mounting Screws, Parallel Key, Safety Cover (with screws), Gasket, Operating Manual
- Solid Shaft Gearhead
Gearhead, Mounting Screws, Parallel Key, Gasket, Operating Manual

Gearmotor – Torque Table

- Gearheads and decimal gearheads are sold separately.
- Enter the code that represents the terminal box type "T" in the box (□) within the motor model name.
- Enter the gear ratio in the box (□) within the gearhead model name.
- A colored background (□) indicates gear shaft rotation in the same direction as the motor shaft, while the others rotate in the opposite direction.
- The speed is calculated by dividing the motor's synchronous speed (50 Hz: 1500 r/min, 60 Hz: 1800 r/min) by the gear ratio. The actual speed is 2~20% less than the displayed value, depending on the load.
- To reduce the speed beyond the gear ratio in the table, attach a decimal gearhead (gear ratio 10:1) between the gearhead and the motor. In that case, the permissible torque is 20 N·m (177 lb-in).

◇ 50 Hz

Unit = Upper values: N-m/Lower values: lb-in

Model Motor/ Gearhead	Speed r/min	500	416	300	250	200	166	120	100	83	60	50	41	30	25	20	16	15	12.5	10	8.3
	Gear Ratio	3	3.6	5	6	7.5	9	12.5	15	18	25	30	36	50	60	75	90	100	120	150	180
5IK60GE-CW2 □E 5IK60GE-ECH	/ 5GE □SA	1.2	1.4	2.0	2.4	3.0	3.6	4.5	5.4	6.4	8.1	9.7	11.6	16.2	19.4	20	20	20	20	20	20
		10.6	12.3	17.7	21	26	31	39	47	56	71	85	102	143	171	177	177	177	177	177	177
5IK60GE-SW2 □ 5IK60GE-SH	/ 5GE □SA	1.1	1.3	1.8	2.2	2.7	3.3	4.1	4.9	5.9	7.4	8.9	10.7	14.9	17.8	19.9	20	20	20	20	20
		9.7	11.5	15.9	19.4	23	29	36	43	52	65	78	94	131	157	176	177	177	177	177	177

◇ 60 Hz

Unit = Upper values: N-m/Lower values: lb-in

Model Motor/ Gearhead	Speed r/min	600	500	360	300	240	200	144	120	100	72	60	50	36	30	24	20	18	15	12	10
	Gear Ratio	3	3.6	5	6	7.5	9	12.5	15	18	25	30	36	50	60	75	90	100	120	150	180
5IK60GE-AW2 □U 5IK60GE-CW2 □E 5IK60GE-FCH 5IK60GE-ECH	/ 5GE □SA	0.98	1.2	1.6	2.0	2.5	3.0	3.7	4.4	5.3	6.7	8.0	9.6	13.4	16.0	17.9	20	20	20	20	20
		8.6	10.6	14.1	17.7	22	26	32	38	46	59	70	84	118	141	158	177	177	177	177	177
5IK60GE-SW2 □ 5IK60GE-SH	/ 5GE □SA	0.92	1.1	1.5	1.8	2.3	2.8	3.5	4.2	5.0	6.3	7.5	9.0	12.5	15.0	16.8	20	20	20	20	20
		8.1	9.7	13.2	15.9	20	24	30	37	44	55	66	79	110	132	148	177	177	177	177	177

Gearmotor – Torque Table When Right-Angle Gearhead is Attached

→ Page A-248

Permissible Overhung Load and Permissible Thrust Load

Motor (Round shaft type) → Page A-16

Gearhead → Page A-16

Permissible Load Inertia J of Gearhead

→ Page A-17


Dimensions Unit = mm (in.)

- Mounting screws are included with gearheads. Dimensions for mounting screws → Page A-310

◇ Lead Wire Type ①

Mass: Motor 2.7 kg (5.9 lb.)

Gearhead 1.5 kg (3.3 lb.)



Motor Model	Gearhead Model	DXF
5IK60GE-AW2U 5IK60GE-CW2E 5IK60GE-SW2	5GE □SA	A455U


- Enter the gear ratio in the box (□) within the model name.

◇ Terminal Box Type ②

Mass: Motor 2.8 kg (6.2 lb.)
Gearhead 1.5 kg (3.3 lb.)

Motor Model	Gearhead Model	DXF
5IK60GE-AW2TU 5IK60GE-CW2TE 5IK60GE-SW2T	5GE□SA	A457U


● Enter the gear ratio in the box (□) within the model name.



- Use cable with a diameter of φ6 ~ φ12 mm (φ0.24 ~ φ0.47 in.).
- Details of terminal box → Page A-314


◇ Key and Key Slot

(The key is included with the gearhead)



◇ Shaft Section of Round Shaft Type

The motor's dimensions (excluding the shaft section) are the same as those of the pinion shaft types.




Motor Model	Mass	DXF
5IK60A-AW2U 5IK60A-CW2E 5IK60A-SW2	2.7 kg (5.9 lb.)	A456
5IK60A-AW2TU 5IK60A-CW2TE 5IK60A-SW2T	2.8 kg (6.2 lb.)	A332

◇ Conduit Box Type ③

Motor Model	Gearhead Model	DXF
5IK60GE-FCH 5IK60GE-ECH	5GE□SA	A904U

● Enter the gear ratio in the box (□) within the model name.


Mass: Motor 3.2 kg (7.0 lb.)
Gearhead 1.5 kg (3.3 lb.)



3 Motor Leads: UL Style 3266, AWG20
1 Ground Lead: UL Style 3266, AWG18
● Details of terminal box → Page A-314

◇ Key and Key Slot


(The key is included with the gearhead)



Motor Model	Gearhead Model	DXF
5IK60GE-SH	5GE□SA	A905U

● Enter the gear ratio in the box (□) within the model name.


Mass: Motor 2.8 kg (6.2 lb.)
Gearhead 1.5kg (3.3 lb.)



3 Motor Leads: UL Style 3266, AWG20
1 Ground Lead: UL Style 3266, AWG18
● Details of terminal box → Page A-314

◇ Key and Key Slot


(The key is included with the gearhead)



◇ Shaft Section of Round Shaft Type

The motor's dimensions (excluding the shaft section) are the same as those of the pinion shaft types.


Motor Model	Mass	DXF
5IK60A-FCH 5IK60A-ECH	3.2 kg (7.0 lb.)	A813



◇ Shaft Section of Round Shaft Type

The motor's dimensions (excluding the shaft section) are the same as those of the pinion shaft types.

Motor Model	Mass	DXF
5IK60A-SH	2.8 kg (6.2 lb.)	A814




◇ Decimal Gearhead

Can be connected to **GE** pinion shaft type.

5GE10XS


Mass: 0.6 kg (1.32 lb.)

DXF A029



◇ Capacitor

(Included with single-phase motors)



◇ Capacitor Dimensions Unit = mm (in.)

Model Upper Model Name: Pinion Shaft Type Lower Model Name (): Round Shaft Type		Capacitor Model	A	B	C	Mass g (oz.)	Capacitor Cap
Lead Wire Type	Terminal Box Type						
5IK60GE-AW2U (5IK60A-AW2U)	5IK60GE-AW2TU (5IK60A-AW2TU)	CH180CFAUL2	58 (2.28)	29 (1.14)	41 (1.61)	92 (3.2)	Included
5IK60GE-CW2E (5IK60A-CW2E)	5IK60GE-CW2TE (5IK60A-CW2TE)	CH40BFAUL	58 (2.28)	23.5 (0.93)	37 (1.46)	73 (2.6)	

Connection Diagrams

- The direction of motor rotation is as viewed from the shaft end of the motor. CW represents the clockwise direction, while CCW represents the counterclockwise direction.
- Connection diagrams are also valid for the equivalent round shaft type.

Lead Wire Type		Terminal Box Type	
<p>5IK60GE-AW2U 5IK60GE-CW2E</p> <p>Clockwise</p> <p>Counterclockwise</p>	<p>5IK60GE-SW2</p> <p>Clockwise</p> <p>Counterclockwise To change the rotation direction, change any two connections between L1(R), L2(S) and L3(T).</p>	<p>5IK60GE-AW2TU 5IK60GE-CW2TE</p> <p>Clockwise</p> <p>Counterclockwise</p>	<p>5IK60GE-SW2T</p> <p>Clockwise</p> <p>Counterclockwise To change the rotation direction, change any two connections between L1(R), L2(S) and L3(T).</p>

Conduit Box Type	
<p>5IK60GE-FCH 5IK60GE-ECH</p> <p>Clockwise</p> <p>Counterclockwise</p>	<p>5IK60GE-SH</p> <p>Clockwise</p> <p>Counterclockwise To change the rotation direction, change any two connections between L1(R), L2(S) and L3(T).</p>

PE: Protective Earth

Note:

- Change the direction of single-phase motor rotation only after bringing the motor to a stop. If an attempt is made to change the direction of rotation while the motor is rotating, motor may ignore reversing command or change its direction of rotation after some delay.
- How to connect a capacitor → Page A-313

Gearhead, Accessories and Peripheral Equipment

<p>Space-Saving Right-Angle Gearheads →Page A-239</p>	<p>Instantaneous Stop Brake Pack →Page A-277</p>	<p>Speed Control Speed Controller →Page B-156</p>	<p>Accessories →Page A-287</p>
---	--	---	------------------------------------

Induction Motors

90 W (1/8 HP)

Frame Size: □90 mm (□3.54 in.)



Lead Wire Type



Terminal Box Type

(Gearhead sold separately)

Specifications – Continuous Rating (RoHS)



Model Upper Model Name: Pinion Shaft Type Lower Model Name (): Round Shaft Type			Output Power	Voltage	Frequency	Current	Starting Torque	Rated Torque	Rated Speed	Capacitor
Lead Wire Type Dimension ①	Terminal Box Type Dimension ②	Conduit Box Type Dimension ③	W HP	VAC	Hz	A	mN·m oz·in	mN·m oz·in	r/min	μF
ⓉP 5IK90GE-AW2U (5IK90A-AW2U)	5IK90GE-AW2TU (5IK90A-AW2TU)	5IK90GE-FCH (5IK90A-FCH)	90 1/8	Single-Phase 110	60	1.45	450	585	1500	20
				Single-Phase 115		1.44		83		
ⓉP 5IK90GE-CW2E (5IK90A-CW2E)	5IK90GE-CW2TE (5IK90A-CW2TE)	5IK90GE-ECH*1 (5IK90A-ECH)*1	90 1/8	Single-Phase 220	50	0.74	450 63	730 103	1200	6.0
				Single-Phase 230	60	0.82		605 85	1450	
					50	0.76		730 103	1200	
				60	0.81	605 85		1450		
ⓉP 5IK90GE-SW2 (5IK90A-SW2)	5IK90GE-SW2T (5IK90A-SW2T)	5IK90GE-SH (5IK90A-SH)	90 1/8	Three-Phase 200	50	0.64	850 120	680 96	1300	-
				Three-Phase 220	60	0.59	700 99	570 80	1550	
					Three-Phase 230	60	0.60	700 99	570 80	
				Three-Phase 230	60	0.61	700 99	570 80	1600	

● The **U** and **E** at the end of the model name indicate that the unit includes a capacitor. These letters are not listed on the motor nameplate.
When the motor is approved under various safety standards, the model name on the nameplate is the approved model name. → Page G-11

● Details of safety standards → Page G-2

● Details of RoHS Directive → Page G-38

*1 Single-Phase 220 VAC 50Hz type is not available for conduit box type.

*2 Conduit box type is not certified under the China Compulsory Certification System (CCC System).

ⓉP: Contains a built-in thermal protector (automatic return type). If a motor overheats for any reason, the thermal protector is activated and the motor is stopped.
When the motor temperature drops, the thermal protector closes and the motor restarts. Be sure to turn the motor power off before inspecting.

Product Line

● Motor (RoHS)

Type	Model	
	Pinion Shaft Type	Round Shaft Type
Lead Wire	5IK90GE-AW2U	5IK90A-AW2U
	5IK90GE-CW2E	5IK90A-CW2E
	5IK90GE-SW2	5IK90A-SW2
Terminal Box	5IK90GE-AW2TU	5IK90A-AW2TU
	5IK90GE-CW2TE	5IK90A-CW2TE
Conduit Box	5IK90GE-SW2T	5IK90A-SW2T
	5IK90GE-FCH	5IK90A-FCH
	5IK90GE-ECH	5IK90A-ECH
	5IK90GE-SH	5IK90A-SH

The following items are included in each product.
Motor, Capacitor*, Capacitor Cap*, Operating Manual
* Only for single-phase motors (Excluding conduit box type)

● Parallel Shaft Gearhead/Right-Angle Gearhead
(Sold separately) (RoHS)

Gearhead Type		Gearhead Model	Gear Ratio
Parallel Shaft	Long Life GE-S Gearhead	5GE□SA	3, 3.6, 5, 6, 7.5, 9, 12.5, 15, 18, 25, 30, 36, 50, 60, 75, 90, 100, 120, 150, 180
	Right-Angle Shaft	Hollow Shaft	
		Solid Shaft	
Parallel Shaft	Long Life GE-S Gearhead	5GE10XS (Decimal Gearhead)	

● Enter the gear ratio in the box (□) within the model name.

The following items are included in each product.

- Parallel Shaft Gearhead
Gearhead, Mounting Screws, Parallel Key, Operating Manual
- Hollow Shaft Gearhead
Gearhead, Mounting Screws, Parallel Key, Safety Cover (with screws), Gasket, Operating Manual
- Solid Shaft Gearhead
Gearhead, Mounting Screws, Parallel Key, Gasket, Operating Manual

Gearmotor – Torque Table

- Gearheads and decimal gearheads are sold separately.
- Enter the code that represents the terminal box type "T" in the box (□) within the motor model name.
- Enter the gear ratio in the box (□) within the gearhead model name.
- A colored background (□) indicates gear shaft rotation in the same direction as the motor shaft, while the others rotate in the opposite direction.
- The speed is calculated by dividing the motor's synchronous speed (50 Hz: 1500 r/min, 60 Hz: 1800 r/min) by the gear ratio. The actual speed is 2~20% less than the displayed value, depending on the load.
- To reduce the speed beyond the gear ratio in the table, attach a decimal gearhead (gear ratio 10:1) between the gearhead and the motor. In that case, the permissible torque is 20 N·m (177 lb-in).

◇ 50 Hz

Unit = Upper values: N·m/Lower values: lb-in

Model Motor/ Gearhead	Speed r/min	500	416	300	250	200	166	120	100	83	60	50	41	30	25	20	16	15	12.5	10	8.3
	Gear Ratio	3	3.6	5	6	7.5	9	12.5	15	18	25	30	36	50	60	75	90	100	120	150	180
5IK90GE-CW2 □E 5IK90GE-ECH	5GE □SA	1.8 15.9	2.1 18.5	3.0 26	3.5 30	4.4 38	5.3 46	6.7 59	8.0 70	9.6 84	12.0 106	14.5 128	17.3 153	20 177	20 177	20 177	20 177	20 177	20 177	20 177	20 177
5IK90GE-SW2 □ 5IK90GE-SH	5GE □SA	1.7 15.0	2.0 17.7	2.8 24	3.3 29	4.1 36	5.0 44	6.2 54	7.4 65	8.9 78	11.2 99	13.5 119	16.2 143	20 177	20 177	20 177	20 177	20 177	20 177	20 177	20 177

◇ 60 Hz

Unit = Upper values: N·m/Lower values: lb-in

Model Motor/ Gearhead	Speed r/min	600	500	360	300	240	200	144	120	100	72	60	50	36	30	24	20	18	15	12	10
	Gear Ratio	3	3.6	5	6	7.5	9	12.5	15	18	25	30	36	50	60	75	90	100	120	150	180
5IK90GE-AW2 □U 5IK90GE-FCH	5GE □SA	1.4 12.3	1.7 15.0	2.4 21	2.8 24	3.6 31	4.3 38	5.3 46	6.4 56	7.7 68	9.7 85	11.6 102	13.9 123	19.3 170	20 177	20 177	20 177	20 177	20 177	20 177	20 177
5IK90GE-CW2 □E 5IK90GE-ECH	5GE □SA	1.5 13.2	1.8 15.9	2.5 22	2.9 25	3.7 32	4.4 38	5.5 48	6.6 58	7.9 69	10.0 88	12.0 106	14.4 127	20 177	20 177	20 177	20 177	20 177	20 177	20 177	20 177
5IK90GE-SW2 □ 5IK90GE-SH	5GE □SA	1.4 12.3	1.7 15.0	2.3 20	2.8 24	3.5 30	4.2 37	5.2 46	6.2 54	7.5 66	9.4 83	11.3 100	13.5 119	18.8 166	20 177	20 177	20 177	20 177	20 177	20 177	20 177

Gearmotor – Torque Table When Right-Angle Gearhead is Attached

→ Page A-248

Permissible Overhung Load and Permissible Thrust Load

Motor (Round shaft type) → Page G-16

Gearhead → Page G-16

Permissible Load Inertia J of Gearhead

→ Page G-17


Dimensions Unit = mm (in.)

- Mounting screws are included with gearheads. Dimensions for mounting screws → Page A-310

◇ Lead Wire Type ①

Mass: Motor 3.2 kg (7.0 lb.)

Gearhead 1.5 kg (3.3 lb.)



Motor Model	Gearhead Model	DXF
5IK90GE-AW2U 5IK90GE-CW2E 5IK90GE-SW2	5GE □SA	A458U


- Enter the gear ratio in the box (□) within the model name.

◇ Terminal Box Type ②

Mass: Motor 3.3 kg (7.3 lb.)
Gearhead 1.5 kg (3.3 lb.)

Motor Model	Gearhead Model	DXF
5IK90GE-AW2TU 5IK90GE-CW2TE 5IK90GE-SW2T	5GE□SA	A460U


● Enter the gear ratio in the box (□) within the model name.



- Use cable with a diameter of $\phi 6 \sim \phi 12$ mm ($\phi 0.24 \sim \phi 0.47$ in.).
- Details of terminal box → Page A-314

◇ Key and Key Slot


(The key is included with the gearhead)



◇ Shaft Section of Round Shaft Type

The motor's dimensions (excluding the shaft section) are the same as those of the pinion shaft types.

Motor Model	Mass	DXF
5IK90A-AW2U 5IK90A-CW2E 5IK90A-SW2	3.2 kg (7.0 lb.)	A459
5IK90A-AW2TU 5IK90A-CW2TE 5IK90A-SW2T	3.3 kg (7.3 lb.)	A334




◇ Conduit Box Type ③

Motor Model	Gearhead Model	DXF
5IK90GE-FCH 5IK90GE-ECH	5GE□SA	A906U

● Enter the gear ratio in the box (□) within the model name.


Mass: Motor 3.7 kg (8.1 lb.)
Gearhead 1.5 kg (3.3 lb.)



3 Motor Leads: UL Style 3266, AWG20
1 Ground Lead: UL Style 3266, AWG18
● Details of terminal box → Page A-314

◇ Key and Key Slot


(The key is included with the gearhead)



Motor Model	Gearhead Model	DXF
5IK90GE-SH	5GE□SA	A907U

● Enter the gear ratio in the box (□) within the model name.


Mass: Motor 3.3 kg (7.3 lb.)
Gearhead 1.5 kg (3.3 lb.)



3 Motor Leads: UL Style 3266, AWG20
1 Ground Lead: UL Style 3266, AWG18
● Details of terminal box → Page A-314

◇ Key and Key Slot


(The key is included with the gearhead)



◇ Shaft Section of Round Shaft Type

The motor's dimensions (excluding the shaft section) are the same as those of the pinion shaft types.


Motor Model	Mass	DXF
5IK90A-FCH 5IK90A-ECH	3.7 kg (8.1 lb.)	A815



◇ Shaft Section of Round Shaft Type

The motor's dimensions (excluding the shaft section) are the same as those of the pinion shaft types.

Motor Model	Mass	DXF
5IK90A-SH	3.3 kg (7.3 lb.)	A816




◇ Decimal Gearhead

Can be connected to **GE** pinion shaft type.

5GE10XS


Mass: 0.6 kg (1.32 lb.)

DXF A029



◇ Capacitor

(Included with single-phase motors)



◇ Capacitor Dimensions Unit = mm (in.)

Model		Capacitor Model	A	B	C	Mass g (oz.)	Capacitor Cap
Upper Model Name: Pinion Shaft Type	Lower Model Name (): Round Shaft Type						
Lead Wire Type	Terminal Box Type						
5IK90GE-AW2U (5IK90A-AW2U)	5IK90GE-AW2TU (5IK90A-AW2TU)	CH200CFAUL2	58 (2.28)	29 (1.14)	41 (1.61)	91 (3.2)	Included
5IK90GE-CW2E (5IK90A-CW2E)	5IK90GE-CW2TE (5IK90A-CW2TE)	CH60BFAUL	58 (2.28)	29 (1.14)	41 (1.61)	92 (3.2)	

Connection Diagrams

- The direction of motor rotation is as viewed from the shaft end of the motor. CW represents the clockwise direction, while CCW represents the counterclockwise direction.
- Connection diagrams are also valid for the equivalent round shaft type.

Lead Wire Type		Terminal Box Type	
5IK90GE-AW2U 5IK90GE-CW2E	5IK90GE-SW2	5IK90GE-AW2TU 5IK90GE-CW2TE	5IK90GE-SW2T
<p>Clockwise</p>	<p>Clockwise</p>	<p>Clockwise</p>	<p>Clockwise</p>
<p>Counterclockwise</p>	<p>Counterclockwise</p> <p>To change the rotation direction, change any two connections between L1(R), L2(S) and L3(T).</p>	<p>Counterclockwise</p>	<p>Counterclockwise</p> <p>To change the rotation direction, change any two connections between L1(R), L2(S) and L3(T).</p>

Conduit Box Type	
5IK90GE-FCH 5IK90GE-ECH	5IK90GE-SH
<p>Clockwise</p> <p>*NC: No connection</p>	<p>Clockwise</p>
<p>Counterclockwise</p> <p>*NC: No connection</p>	<p>Counterclockwise</p> <p>To change the rotation direction, change any two connections between L1(R), L2(S) and L3(T).</p>

PE: Protective Earth

Note:

- Change the direction of single-phase motor rotation only after bringing the motor to a stop. If an attempt is made to change the direction of rotation while the motor is rotating, motor may ignore reversing command or change its direction of rotation after some delay.
- How to connect a capacitor → Page A-313


Gearhead, Accessories and Peripheral Equipment

<p>Space-Saving Right-Angle Gearheads →Page A-239</p>	<p>Instantaneous Stop Brake Pack →Page A-277</p>	<p>Speed Control Speed Controller →Page B-156</p>	<p>Accessories →Page A-287</p>
---	--	---	------------------------------------

High Power Induction Motors BH Series

200 W (1/4 HP)

Frame Size: □104 mm (□4.09 in.)

Cable Type
Right-Angle Hollow ShaftTerminal Box Type
Parallel Shaft

Features

● High Power 200 W (1/4 HP)

Smallest frame size among 200 W (1/4 HP) motors

● Hypoid Gear-Employed Right-Angle Gearheads

Right-angle gearheads employ hypoid gears. Hollow shafts and solid shafts are available to enable space-saving.

● (RoHS) RoHS-Compliant

The BH Series conforms to the RoHS Directive that prohibits the use of six chemical substances including lead and cadmium.

● Details of RoHS Directive → Page G-38

● "Combination Type" for Easy Installation

The combination type comes with the motor and gearhead pre-assembled. This enables easy installation in equipment.

Combination Type:

The combination type comes with the motor and its dedicated gearhead pre-assembled, which simplifies installation in equipment. Motors and gearheads are also available separately to facilitate changes or repairs.

Specifications – Continuous Rating (RoHS)



Model Combination Type () : Round Shaft Type	Output Power W HP	Voltage VAC	Frequency Hz	Current A	Starting Torque N·m oz·in	Rated Torque N·m oz·in	Rated Speed r/min	Capacitor μF
(TP) BHI62F-□RH BHI62F-□RA BHI62F-□ (BHI62F-A)	200 1/4	Single-Phase 110	60	3	0.88 124	1.27 180	1500	40
(TP) BHI62E-□RH BHI62E-□RA BHI62E-□ (BHI62E-A)	200 1/4	Single-Phase 220	60	1.5	0.98 139	1.27 180	1500	10
		Single-Phase 230	50			1.52 210		
		Single-Phase 230	60			1.27 180		
(TP) —	200 1/4	Three-Phase 200	50	1.1	1.49 210	1.49 210	1250	—
			60					
		Three-Phase 220	60	0.95	1.23 174	1.23 174	1550	
			60					
		Three-Phase 230	60	0.95	1.18 167	1.18 167	1600	
			60					

● Enter the gear ratio in the box (□) within the model name. The values for each specification applies to the motor only.

● Details of safety standards → Page G-2

● List of safety standard approved products (Model, Standards, Standards File No., Certification Body) → Page G-11

(TP): Contains a built-in thermal protector (automatic return type). If a motor overheats for any reason, the thermal protector is activated and the motor is stopped. When the motor temperature drops, the thermal protector closes and the motor restarts. Be sure to turn the motor power off before inspecting.

Product Line

● Combination Type (RoHS)

◇ Right-Angle Shaft

Type	Voltage	Model	Gear Ratio
Hollow Shaft Cable	Single-Phase 110/115 VAC	BHI62F-□RH	5, 6, 7.5, 9, 12.5, 15, 18, 25, 30, 36, 50, 60, 75, 90, 100, 120, 150, 180
	Single-Phase 220/230 VAC	BHI62E-□RH	
Hollow Shaft Terminal Box	Single-Phase 110/115 VAC	BHI62FT-□RH	
	Single-Phase 220/230 VAC	BHI62ET-□RH	
Solid Shaft Cable	Single-Phase 110/115 VAC	BHI62F-□RA	
	Single-Phase 220/230 VAC	BHI62E-□RA	
Solid Shaft Terminal Box	Single-Phase 110/115 VAC	BHI62FT-□RA	
	Single-Phase 220/230 VAC	BHI62ET-□RA	
	Three-Phase 200/220/230 VAC	BHI62ST-□RA	

● Enter the gear ratio in the box (□) within the model name.

The following items are included in each product. —

Motor, Gearhead, Capacitor*, Capacitor Cap*, Parallel Key, Operating Manual

* Only for single-phase motors

◇ Parallel Shaft

Type	Voltage	Model	Gear Ratio
Parallel Shaft Cable	Single-Phase 110/115 VAC	BHI62F -□	3, 3.6, 5, 6, 7.5, 9, 12.5, 15, 18, 25, 30, 36, 50, 60, 75, 90, 100, 120, 150, 180
	Single-Phase 220/230 VAC	BHI62E -□	
Parallel Shaft Terminal Box	Single-Phase 110/115 VAC	BHI62FT -□	
	Single-Phase 220/230 VAC	BHI62ET -□	
	Three-Phase 200/220/230 VAC	BHI62ST -□	

● Enter the gear ratio in the box (□) within the model name.

The following items are included in each product.
 Motor, Gearhead, Capacitor*, Capacitor Cap*, Mounting Screws, Parallel Key, Operating Manual
 * Only for single-phase motors

● Round Shaft Type (RoHS)

Type	Voltage	Model
Cable	Single-Phase 110/115 VAC	BHI62F-A
	Single-Phase 220/230 VAC	BHI62E-A
Terminal Box	Single-Phase 110/115 VAC	BHI62FT-A
	Single-Phase 220/230 VAC	BHI62ET-A
	Three-Phase 200/220/230 VAC	BHI62ST-A

The following items are included in each product.
 Motor, Capacitor*, Capacitor Cap*, Operating Manual
 * Only for single-phase motors

■ Gearmotor – Torque Table for Combination Type

- Enter the code that represents the terminal box type “T” in the box (□) within the model name.
- Enter the gear ratio in the box (□) within the model name.
- A colored background (□) indicates gear shaft rotation in the same direction as the motor shaft, while the others rotate in the opposite direction.
- The speed is calculated by dividing the motor's synchronous speed (50 Hz: 1500 r/min, 60 Hz: 1800 r/min) by the gear ratio. The actual speed is 2~20% less than the displayed value, depending on the load.
- Decimal gearheads are not available for the **BH** series.

● Right-Angle Shaft 50 Hz

Unit = Upper values: N-m/Lower values: lb-in

Model	Speed r/min	300	250	200	167	120	100	83	60	50	42	30	25	20	17	15	12.5	10	8.3
	Gear Ratio	5	6	7.5	9	12.5	15	18	25	30	36	50	60	75	90	100	120	150	180
BHI62E -□-□RH, BHI62E -□-□RA	5.5 48	6.7 59	8.3 73	10.0 88	13.9 123	16.6 146	20.0 177	27.7 240	33.3 290	36.0 310	40.0 350	43.0 380	47.0 410	51.5 450	54.5 480	60 530	60 530	60 530	
BHI62ST -□RH, BHI62ST -□RA	5.4 47	6.5 57	8.2 72	9.8 86	13.6 120	16.3 144	19.6 173	27.2 240	32.6 280	36.0 310	40.0 350	43.0 380	47.0 410	51.5 450	54.5 480	60 530	60 530	60 530	

● Right-Angle Shaft 60 Hz

Unit = Upper values: N-m/Lower values: lb-in

Model	Speed r/min	360	300	240	200	144	120	100	72	60	50	36	30	24	20	18	15	12	10
	Gear Ratio	5	6	7.5	9	12.5	15	18	25	30	36	50	60	75	90	100	120	150	180
BHI62F -□-□RH, BHI62F -□-□RA BHI62E -□-□RH, BHI62E -□-□RA	4.6 40	5.6 49	7.0 61	8.3 73	11.6 102	13.9 123	16.7 147	23.2 200	27.8 240	33.4 290	40.0 350	43.0 380	47.0 410	51.5 450	54.5 480	60 530	60 530	60 530	
BHI62ST -□RH, BHI62ST -□RA (200 VAC)	4.6 40	5.5 48	6.8 60	8.2 72	11.4 100	13.7 121	16.4 145	22.8 200	27.4 240	32.9 290	40.0 350	43.0 380	47.0 410	51.5 450	54.5 480	60 530	60 530	60 530	
BHI62ST -□RH, BHI62ST -□RA (220 VAC)	4.5 39	5.4 47	6.7 59	8.1 71	11.2 99	13.5 119	16.2 143	22.4 198	27.0 230	32.3 280	40.0 350	43.0 380	47.0 410	51.5 450	54.5 480	60 530	60 530	60 530	
BHI62ST -□RH, BHI62ST -□RA (230 VAC)	4.3 38	5.2 46	6.5 57	7.8 69	10.8 95	12.9 114	15.5 137	21.5 190	25.8 220	31.0 270	40.0 350	43.0 380	47.0 410	51.5 450	54.5 480	60 530	60 530	60 530	

● Parallel Shaft 50 Hz

Unit = Upper values: N-m/Lower values: lb-in

Model	Speed r/min	500	417	300	250	200	167	120	100	83	60	50	42	30	25	20	17	15	12.5	10	8.3
	Gear Ratio	3	3.6	5	6	7.5	9	12.5	15	18	25	30	36	50	60	75	90	100	120	150	180
BHI62E -□-□	4.1 36	4.9 43	6.8 60	8.2 72	10.3 91	12.3 108	16.3 144	19.6 173	23.5 200	32.7 280	39.2 340	40 350	40 350	40 350	40 350	40 350	40 350	40 350	40 350	40 350	40 350
BHI62ST -□	4.0 35	4.8 42	6.7 59	8.0 70	10.1 89	12.1 107	16.0 141	19.2 169	23.1 200	32.0 280	38.4 330	40 350	40 350	40 350	40 350	40 350	40 350	40 350	40 350	40 350	40 350

● Parallel Shaft 60 Hz

Unit = Upper values: N-m/Lower values: lb-in

Model	Speed r/min	600	500	360	300	240	200	144	120	100	72	60	50	36	30	24	20	18	15	12	10
	Gear Ratio	3	3.6	5	6	7.5	9	12.5	15	18	25	30	36	50	60	75	90	100	120	150	180
BHI62F -□-□, BHI62E -□-□	3.4 30	4.1 36	5.7 50	6.9 61	8.6 76	10.3 91	13.7 121	16.4 145	19.7 174	27.3 240	32.8 290	39.3 340	40 350	40 350	40 350	40 350	40 350	40 350	40 350	40 350	40 350
BHI62ST -□ (200 VAC)	3.4 30	4.1 36	5.6 49	6.8 60	8.4 74	10.1 89	13.4 118	16.1 142	19.4 171	26.9 230	32.3 280	38.7 340	40 350	40 350	40 350	40 350	40 350	40 350	40 350	40 350	40 350
BHI62ST -□ (220 VAC)	3.3 29	4.0 35	5.5 48	6.6 58	8.3 73	10.0 88	13.2 116	15.9 140	19.0 168	26.4 230	31.7 280	38.1 330	40 350	40 350	40 350	40 350	40 350	40 350	40 350	40 350	40 350
BHI62ST -□ (230 VAC)	3.2 28	3.8 33	5.3 46	6.4 56	8.0 70	9.6 84	12.7 112	15.2 134	18.3 161	25.4 220	30.4 260	36.5 320	40 350	40 350	40 350	40 350	40 350	40 350	40 350	40 350	40 350

Permissible Overhung Load and Permissible Thrust Load

Combination Type → Page A-16

Round Shaft Type → Page A-16

Permissible Load Inertia J of Gearhead

→ Page A-17

Dimensions Unit = mm (in.)

● Mounting screws are included with the combination type, parallel shaft. Dimensions for mounting screws → Page A-310

◇ Combination Type: Right-Angle, Hollow Shaft (Cable Type)

BHI62F-□RH, BHI62E-□RH

Mass: 10.0 kg (22 lb.)




Motor: BHI62F-G2, BHI62E-G2

Gearhead: BH6G2-□RH


DXF A299

◇ Key

(The key is included with the gearhead)



Motor Cable
 $\phi 7.8$ ($\phi 0.31$), 500 mm (20 in.) Length
 UL Style 3271, AWG20



● Enter the gear ratio in the box (□) within the model name.

◇ Combination Type: Right-Angle, Solid Shaft (Cable Type)


BHI62F-□RA, BHI62E-□RA

Mass: 10.0 kg (22 lb.)


Motor: BHI62F-G2, BHI62E-G2

Gearhead: BH6G2-□RA

DXF A300



◇ Key and Key Slot



● At the time of shipment, a key is inserted on the gearhead's shaft.

● Enter the gear ratio in the box (□) within the model name.

◇ Combination Type: Right-Angle, Hollow Shaft (Terminal Box Type)

BHI62FT-□RH, BHI62ET-□RH, BHI62ST-□RH

Mass: 10.0 kg (22 lb.)




Motor: BHI62FT-G2, BHI62ET-G2, BHI62ST-G2

Gearhead: BH6G2-□RH

DXF A301

◇ Key

(The key is included with the gearhead)



- Use cable with a diameter of $\phi 6 \sim \phi 12$ mm ($\phi 0.24 \sim \phi 0.47$ in.).
- Details of terminal box → Page A-314

● Enter the gear ratio in the box (□) within the model name.

◇ Combination Type: Right-Angle, Solid Shaft (Terminal Box Type)


BHI62FT-□RA, BHI62ET-□RA, BHI62ST-□RA

Mass: 10.0 kg (22 lb.)

Motor: BHI62FT-G2, BHI62ET-G2, BHI62ST-G2


Gearhead: BH6G2-□RA

DXF A302



- Use cable with a diameter of $\phi 6 \sim \phi 12$ mm ($\phi 0.24 \sim \phi 0.47$ in.).
- Details of terminal box → Page A-314

◇ Key and Key Slot



- At the time of shipment, a key is inserted on the gearhead's shaft.

- Enter the gear ratio in the box (□) within the model name.

- 1 W (3 W)
(1/750 HP)
(1/250 HP)
- 6 W
(1/125 HP)
- 15 W
(1/50 HP)
- 25 W
(1/30 HP)
- 40 W
(1/19 HP)
- 60 W
(1/12 HP)
- 90 W
(1/8 HP)
- 200 W
(1/4 HP)
- 2-Pole
40-150 W
(1/3-1/5 HP)

◇ Combination Type: Parallel Shaft (Terminal Box Type)


BHI62F-□, BHI62E-□

Mass: 8.0 kg (18 lb.)

Motor: BHI62F-G2, BHI62E-G2

Gearhead: BH6G2-□

DXF A303




BHI62FT-□, BHI62ET-□, BHI62ST-□

Mass: 8.0 kg (18 lb.)

Motor: BHI62FT-G2, BHI62ET-G2, BHI62ST-G2

Gearhead: BH6G2-□


DXF A304



● Use cable with a diameter of $\phi 6 \sim \phi 12$ mm ($\phi 0.24 \sim \phi 0.47$ in.).

● Details of terminal box → Page A-314

◇ Key and Key Slot



● At the time of shipment, a key is inserted on the gearhead's shaft.


● Enter the gear ratio in the box (□) within the model name.

◇ Round Shaft Type (Cable Type)

BHI62F-A, BHI62E-A

Mass: 5.0 kg (11 lb.)

DXF A307




◇ Round Shaft Type (Terminal Box Type)

BHI62FT-A, BHI62ET-A, BHI62ST-A


Mass: 5.0 kg (11 lb.)

DXF A308



- Use cable with a diameter of $\phi 6 \sim \phi 12$ mm ($\phi 0.24 \sim \phi 0.47$ in.).
- Details of terminal box → Page A-314

◇ Capacitor (Included with single-phase motors)



◇ Capacitor Dimensions Unit = mm (in.)

Model		Capacitor Model	A	B	C	Mass g (oz.)	Capacitor Cap
Cable Type	Terminal Box Type						
BHI62F-□RH BHI62F-□RA BHI62F-□ BHI62F-A	BHI62FT-□RH BHI62FT-□RA BHI62FT-□ BHI62FT-A	CH400CFAUL2	58 (2.28)	41 (1.61)	58 (2.28)	175 (6.2)	Included
BHI62E-□RH BHI62E-□RA BHI62E-□ BHI62E-A	BHI62ET-□RH BHI62ET-□RA BHI62ET-□ BHI62ET-A	CH100BFAUL	58 (2.28)	35 (1.38)	50 (1.97)	132 (4.7)	

● Enter the gear ratio in the box (□) within the model name.

■ Mounting Method for Right-Angle, Hollow Shaft Types

These figures below show how to mount loads depending on the shape of the shaft. The tolerance of the inner diameter for the hollow shaft is finished as shown in the table on the right, and “key slot” processing is given to mount the load shaft. Use the key provided with the product by fastening it to the shaft. Apply a coating of molybdenum disulfide or similar grease to the surface of the load shaft and to the inner diameter of the load shaft to prevent sticking. Recommended load shaft diameter and inner diameter of hollow shaft are shown in the table on the right.


● Inner Diameter of Hollow Shaft and Recommended Load Shaft Diameter

Unit = mm (in.)

Model	BH6G2-□RH
Inner Diameter of Hollow Shaft H8	$\phi 25^{+0.033}_0$ ($\phi 0.9843^{+0.0013}_0$)
Recommended Load Shaft Diameter h7	$\phi 25^0_{-0.021}$ ($\phi 0.9843^0_{-0.0008}$)

● Enter the gear ratio in the box (□) within the model name.

● Stepped Load Shaft




● After securing a load, attach the safety cover included.

Notes:

- Be careful not to apply a shock to the hollow shaft when mounting a load shaft. It may damage the bearing inside the gearhead.
- Bolts or other fasteners used to install the load shaft are not included. These parts must be purchased separately.

● Straight Load Shaft



Connection Diagrams

- The direction of motor rotation is as viewed from the shaft end of the motor. CW represents the clockwise direction, while CCW represents the counterclockwise direction.
- Enter the voltage (**F**, **E**) in the box (□) within the model name.

Motor Type	Single-Phase Induction Motor		Three-Phase Induction Motor
	Cable Type BHI62□-3~9 BHI62□-50~180	Terminal Box Type* BHI62□T-3~9 BHI62□T-50~180	Terminal Box Type* BHI62ST-3~9 BHI62ST-50~180
Combination Type: Parallel Shaft	Clockwise CW 	Clockwise CW 	Clockwise CW
	Counterclockwise CCW 	Counterclockwise CCW 	Counterclockwise To change the rotation direction, change any two connections between L1(R), L2(S) and L3(T).
	BHI62□-12.5~36	BHI62□T-12.5~36	BHI62ST-12.5~36
	Clockwise CW 	Clockwise CW 	Clockwise CW
	Counterclockwise CCW 	Counterclockwise CCW 	Counterclockwise To change the rotation direction, change any two connections between L1(S), L2(R) and L3(T).

PE: Protective Earth

* Connecting to the terminal

Applicable lead wires: AWG24~12

Strip length: 8 mm (0.315 in.)

Note:

- Change the direction of single-phase motor rotation only after bringing the motor to a stop. If an attempt is made to change the direction of rotation while the motor is rotating, motor may ignore reversing command or change its direction of rotation after some delay.

- How to connect a capacitor → Page A-313

1 W, 3 W
(1/750 HP,
1/250 HP)

6 W
(1/125 HP)

15 W
(1/50 HP)

25 W
(1/30 HP)

40 W
(1/19 HP)

60 W
(1/12 HP)

90 W
(1/8 HP)

200 W
(1/4 HP)

2-Pole
40-150 W
(1/9-1/5 HP)

Motor Type	Single-Phase Induction Motor		Three-Phase Induction Motor
	Cable Type	Terminal Box Type*	Terminal Box Type*
Combination Type: Right Angle Shaft	BHI62□-5RH~180RH BHI62□-5RA~180RA	BHI62□T-5RH~180RH BHI62□T-5RA~180RA	BHI62ST-5RH~180RH BHI62ST-5RA~180RA
	Clockwise 	Clockwise 	Clockwise
	Counterclockwise 	Counterclockwise 	Counterclockwise To change the rotation direction, change any two connections between L1(S), L2(R) and L3(T).
Round Shaft Type	BHI62□-A	BHI62□T-A	BHI62ST-A
	Clockwise 	Clockwise 	Clockwise
	Counterclockwise 	Counterclockwise 	Counterclockwise To change the rotation direction, change any two connections between L1(R), L2(S) and L3(T).

PE: Protective Earth

* Connecting to the terminal
 Applicable lead wires: AWG24~12
 Strip length: 8 mm (0.315 in.)

Note:

● Change the direction of single-phase motor rotation only after bringing the motor to a stop. If an attempt is made to change the direction of rotation while the motor is rotating, motor may ignore reversing command or change its direction of rotation after some delay.

● How to connect a capacitor → Page A-313

List of Motor and Gearhead Combinations

Motor and gearhead combinations are shown below.

● Combination Type: Right Angle Shaft

Model	Motor Model	Gearhead Model
BHI62F-□RH	BHI62F-G2	BH6G2-□RH
BHI62F-□RA		BH6G2-□RA
BHI62FT-□RH	BHI62FT-G2	BH6G2-□RH
BHI62FT-□RA		BH6G2-□RA
BHI62E-□RH	BHI62E-G2	BH6G2-□RH
BHI62E-□RA		BH6G2-□RA
BHI62ET-□RH	BHI62ET-G2	BH6G2-□RH
BHI62ET-□RA		BH6G2-□RA
BHI62ST-□RH	BHI62ST-G2	BH6G2-□RH
BHI62ST-□RA		BH6G2-□RA

● Enter the gear ratio in the box (□) within the model name.

● Combination Type: Parallel Shaft

Model	Motor Model	Gearhead Model
BHI62F-□	BHI62F-G2	BH6G2-□
BHI62FT-□	BHI62FT-G2	
BHI62E-□	BHI62E-G2	
BHI62ET-□	BHI62ET-G2	
BHI62ST-□	BHI62ST-G2	

● Enter the gear ratio in the box (□) within the model name.

Accessories and Peripheral Equipment

Speed Control
Speed Controller
→ Page B-156



Accessories




→ Page A-287

Induction Motors 2-Pole, High-Speed Type

40 W (1/19 HP), 60 W (1/12 HP), 90 W (1/8 HP), 150 W (1/5 HP)

Frame Size: □80 mm (□3.15 in.), □90 mm (□3.54 in.)



Specifications – Continuous Rating (RoHS)

Model	Output Power		Voltage	Frequency	Current	Starting Torque		Rated Torque		Rated Speed	Capacitor
	W	HP	VAC	Hz	A	mN·m	oz·in	mN·m	oz·in	r/min	μF
Round Shaft Type											
TP 4IK40A-BW2U	40	1/19	Single-Phase 110	60	0.68	90	12.7	135	19.1	2900	7.5
			Single-Phase 115		0.66						
TP 4IK40A-DW3E	36	1/20	Single-Phase 220	50	0.30	90	12.7	145	20	2400	1.8
				60	0.31			120	17.0	2900	
	40	1/19	Single-Phase 230	50	0.33			160	22	2400	
				60	0.32			135	19.1	2900	
TP 4IK60A-BW2U	60	1/12	Single-Phase 110	60	0.98	160	22	190	26	3000	10
			Single-Phase 115		0.97						
TP 4IK60A-DW3E	55	1/14	Single-Phase 220	50	0.44	160	22	210	29	2500	2.5
				60	0.51			180	25	3000	
	60	1/12	Single-Phase 230	50	0.47			230	32	2500	
				60	0.52			190	26	3000	
TP 5IK60A-BW2U	60	1/12	Single-Phase 110	60	0.94	140	19.8	185	26	3200	14
			Single-Phase 115		0.93						
TP 5IK60A-DW3E	60	1/12	Single-Phase 220	50	0.46	120	17.0	220	31	2650	3.0
				60				185	26	3200	
			Single-Phase 230	50	0.45	140	19.8	220	31	2650	
				60				185	26	3200	
TP 5IK60A-TW2	60	1/12	Three-Phase 200	50	0.47	270	38	220	31	2650	-
				60	0.40	230	32	185	26	3200	
			Three-Phase 220	60	0.42	230	32	185	26	3200	
				60	0.44	230	32	185	26	3200	
TP 5IK90A-BW2U	90	1/8	Single-Phase 110	60	1.61	240	34	280	39	3200	25
			Single-Phase 115		1.57						
TP 5IK90A-DW3E	90	1/8	Single-Phase 220	50	0.70	240	34	330	46	2650	6.0
				60	0.84			280	39	3200	
			Single-Phase 230	50	0.69			330	46	2650	
				60	0.84			280	39	3200	
TP 5IK90A-TW2	90	1/8	Three-Phase 200	50	0.63	500	71	340	48	2600	-
				60	0.55	400	56	285	40	3100	
			Three-Phase 220	60	0.57	400	56	285	40	3200	
TP 5IK90A-TW2	90	1/8	Three-Phase 230	60	0.59	400	56	285	40	3200	-
				60	0.59	400	56	285	40	3200	
				60	0.59	400	56	285	40	3200	
TP 5IK150A-BW2U	150	1/5	Single-Phase 110	60	2.12	380	53	460	65	3200	30
			Single-Phase 115		2.09						
TP 5IK150A-DW3E	140	1/5	Single-Phase 220	50	0.98	380	53	510	72	2650	8.0
				60	1.07			420	59	3200	
	150	1/5	Single-Phase 230	50	1.04			560	79	2650	
				60	1.13			460	65	3200	
TP 5IK150A-TW2 5IK150A-TW2T	150	1/5	Three-Phase 200	50	1.11	680	96	550	78	2650	-
				60	0.93	570	80	460	65	3100	
			Three-Phase 220	60	0.97	570	80	460	65	3150	
				60	1.01	570	80	460	65	3200	

● The **U** and **E** at the end of the model name indicate that the unit includes a capacitor. These letters are not listed on the motor nameplate. When the motor is approved under various safety standards, the model name on the nameplate is the approved model name. → Page G-11

● Details of safety standards → Page G-2

● Details of RoHS Directive → Page G-38

ⓉP: Contains a built-in thermal protector (automatic return type). If a motor overheats for any reason, the thermal protector is activated and the motor is stopped. When the motor temperature drops, the thermal protector closes and the motor restarts. Be sure to turn the motor power off before inspecting.

Product Line

Motor **RoHS**

Output Power	Voltage	Model
40 W (1/19 HP)	Single-Phase 110/115 VAC	4IK40A-BW2U
	Single-Phase 220/230 VAC	4IK40A-DW3E
60 W (1/12 HP)	Single-Phase 110/115 VAC	4IK60A-BW2U
	Single-Phase 220/230 VAC	4IK60A-DW3E
	Single-Phase 110/115 VAC	5IK60A-BW2U
	Single-Phase 220/230 VAC	5IK60A-DW3E
90 W (1/8 HP)	Three-Phase 200/220/230 VAC	5IK60A-TW2
	Single-Phase 110/115 VAC	5IK90A-BW2U
	Single-Phase 220/230 VAC	5IK90A-DW3E
150 W (1/5 HP)	Three-Phase 200/220/230 VAC	5IK90A-TW2
	Single-Phase 110/115 VAC	5IK150A-BW2U
	Single-Phase 220/230 VAC	5IK150A-DW3E
	Three-Phase 200/220/230 VAC	5IK150A-TW2T



The following items are included in each product.
 Motor, Capacitor*, Capacitor Cap*, Operating Manual
 * Only for single-phase motors

Dimensions Unit = mm (in.)

40 W (1/19 HP)
4IK40A-BW2U, 4IK40A-DW3E

Mass: 1.5 kg (3.3 lb.)



DXF A450



60 W (1/12 HP)
4IK60A-BW2U, 4IK60A-DW3E

Mass: 1.8 kg (4.0 lb.)

DXF A513



1 W (1/750 HP)
1/250 HP

6 W (1/125 HP)

15 W (1/50 HP)

25 W (1/30 HP)

40 W (1/19 HP)

50 W (1/12 HP)

90 W (1/8 HP)



200 W (1/4 HP)

2-Pole
40-150 W (1/3-1/5 HP)

5IK60A-BW2U, 5IK60A-DW3E, 5IK60A-TW2

Mass: 2.5 kg (5.5 lb.)

DXF A453





Detail Drawing of Protective Earth Terminal

90 W (1/8 HP)

5IK90A-BW2U, 5IK90A-DW3E, 5IK90A-TW2

Mass: 2.7 kg (5.9 lb.)

DXF A456





Detail Drawing of Protective Earth Terminal

150 W (1/5 HP)

5IK150A-BW2U, 5IK150A-DW3E, 5IK150A-TW2

Mass: 3.2 kg (7.0 lb.)

DXF A459




Detail Drawing of Protective Earth Terminal

5IK150A-TW2T


Mass: 3.3 kg (7.3 lb.)

DXF A334



- Use cable with a diameter of $\phi 6 \sim \phi 12$ mm ($\phi 0.24 \sim \phi 0.47$ in.).
- Details of terminal box → Page A-314

● Capacitor (Included with single-phase motors)



◇ Capacitor Dimensions Unit = mm (in.)

Model	Capacitor Model	A	B	C	Mass g (oz.)	Dimension No.	Capacitor Cap
4IK40A-BW2U	CH75CFAUL2	48 (1.89)	21 (0.83)	31 (1.22)	41 (1.45)	①	Included
4IK40A-DW3E	CH18BFAUL	38 (1.50)	21 (0.83)	31 (1.22)	37 (1.31)	①	
4IK60A-BW2U	CH100CFAUL2	58 (2.28)	21 (0.83)	31 (1.22)	49 (1.73)	①	
4IK60A-DW3E	CH25BFAUL	48 (1.89)	21 (0.83)	31 (1.22)	42 (1.48)	①	
5IK60A-BW2U	CH140CFAUL2	58 (2.28)	22 (0.87)	35 (1.38)	61 (2.2)	①	
5IK60A-DW3E	CH30BFAUL	58 (2.28)	21 (0.83)	31 (1.22)	50 (1.77)	①	
5IK90A-BW2U	CH250CFAUL2	58 (2.28)	35 (1.38)	50 (1.97)	140 (4.9)	②	
5IK90A-DW3E	CH60BFAUL	58 (2.28)	29 (1.14)	41 (1.61)	92 (3.2)	②	
5IK150A-BW2U	CH300CFAUL2	58 (2.28)	35 (1.38)	50 (1.97)	140 (4.9)	②	
5IK150A-DW3E	CH80BFAUL	58 (2.28)	35 (1.38)	50 (1.97)	136 (4.6)	②	

Connection Diagrams

● The direction of motor rotation is as viewed from the shaft end of the motor. CW represents the clockwise direction, while CCW represents the counterclockwise direction.

Single-Phase 110/115 VAC Single-Phase 220/230 VAC	Three-Phase 200/220/230 VAC	
	Lead Wire Type	Terminal Box Type
	5IK60A-TW2 5IK90A-TW2 5IK150A-TW2	5IK150A-TW2T
<p>Clockwise</p> <p>Counterclockwise</p>	<p>Clockwise</p> <p>Counterclockwise To change the rotation direction, change any two connections between L1(R), L2(S) and L3(T).</p>	<p>Clockwise</p> <p>Counterclockwise To change the rotation direction, change any two connections between L1(R), L2(S) and L3(T).</p>

PE: Protective Earth

Note:

● Change the direction of single-phase motor rotation only after bringing the motor to a stop.
If an attempt is made to change the direction of rotation while the motor is rotating, motor may ignore reversing command or change its direction of rotation after some delay.

● How to connect a capacitor → Page A-313